UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Dec. 1973	© Budget Bureau No. 42-R1424
UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE 10 10 10 10 10 10 10 10 10 10 10 10 10
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME:
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) 1. Oil gas well other	8. FARM OR LEASE NAME 월 설심을 Atlantic B 설심을 등 도움을
well well other 2. NAME OF OPERATOR	9. WELL NO. 9. 10 10 10 10 10 10 10 10 10 10 10 10 10
EL PASO NATURAL GAS CO. 3. ADDRESS OF OPERATOR	Undes. PC and Blanco MV
BOX 289, FARMINGTON, NEW MEXICO 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34, T-31-N, R-10-W
AT SURFACE: 1500'S, 1825'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE San Juan New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	6278' GL (2004 2004 2004 2004 2004 2004 2004 200
SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE	1 9 g 2 g 2 g 2 g 2 g 2 g 2 g 2 g 2 g 2 g

REPORT, OR OTHER DATA SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES spous spous ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and is of spaur aug poste spurious spuriou spuriou spurious spuriou spuriou spuriou spurious spurious spuriou spuriou spurio measured and true vertical depths for all markers and zones pertinent to this work.)* 1/5/79: Spudded well. Drilled surface hole. Ran 5 joints 9 5/8', 32.3# H-40 surface casing, 204' set at 214'. Cemented with 22% of Circulated to curf Circulated to surface. WOC 12 hours; held 600#/30 minutes. neup audite
in obtain i
per cast of the
cast of the
formal of the Subsurface Safety Valve: Manu. and Type _____ 200 size, i ed off n esize, in 18. I hereby certify that the foregoing is true and correct LLS 20 TITLE Drilling Clerk DATE 1/9/79 1 for the st and the not (This space for Federal or State office use) Any restibbs of frestibbs of fresting biult regulg evode lenoitibnoo APPROVED BY DATE tem 4 CONDITIONS OF APPROVAL, IF ANY:

See Instructions on Reverse Side