

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR  
Northwest Pipeline Corporation
3. ADDRESS OF OPERATOR 87401  
P.O. Box 90, Farmington, New Mexico
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1040' FNL & 1160' FEL  
AT TOP PROD. INTERVAL: same  
AT TOTAL DEPTH: same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: |                          | SUBSEQUENT REPORT OF:    |
|--------------------------|--------------------------|--------------------------|
| TEST WATER SHUT-OFF      | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT           | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE         | <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL              | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING     | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE        | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES             | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON*                 | <input type="checkbox"/> | <input type="checkbox"/> |
| (other)                  | "Drilling summary"       |                          |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*
- 6-14/18-78 Drilled to 3920'. Ran IES & GR Density logs. Ran 134 jts (3903') of 2-7/8", 6.4# csg set @ 3913'. Cmted w/ 160 sks & tailed in w/ 50 sks Cl"B". Displaced plug w/ 1 bbl acetic acid & 29.5 bbls water. Plug down 0400 hrs 6-19-78
- 6-19-78 WOC. Pressure tested 2-7/8" csg to 4000 psi for 15 min, held OK. Released rig 0600 hrs. Top of cmt by temp survey @ 2450'.

Waiting on completion.

JUN 28 1978

U.S. GEOLOGICAL SURVEY  
FARMINGTON, N.M.

Subsurface Safety Valve: Manu. and Type

Set @

18. I hereby certify that the foregoing is true and correct

SIGNED Richard Rex TITLE Production Clerk DATE June 26, 1978

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

5. LEASE  
SF 078543
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME  
San Juan 32-7 Unit
8. FARM OR LEASE NAME  
San Juan 32-7 Unit
9. WELL NO.  
47
10. FIELD OR WILDCAT NAME  
Pictured Cliffs - Undesignated
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec 35 T32N R7W
12. COUNTY OR PARISH  
San Juan
13. STATE  
New Mex
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
6723'GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

