

Denny Faust
DISTRICT 1
DEPUTY OIL & GAS INSPECTOR
P.O. District 1, Artesia, NM 88211
DISTRICT 1
MAR 1-2 1997
1300 Rio Grande St., Artesia, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

(Revised 1/9/94)

Approved

PIT REMEDIATION AND CLOSURE REPORT

Operator: <u>MARATHON OIL COMPANY</u>		Telephone: <u>(915) 682-1626</u>
Address: <u>125 N. MISSOURI AVENUE, MIDLAND, TX 79701</u>		
Facility or: <u>OHIO "F" GOVERNMENT # 1A</u>		
Well Name		
Location: Unit or Qtr/Qtr Sec <u>C</u> Sec <u>20</u> T <u>31N</u> R <u>12W</u> County <u>SAN JUAN</u>		
Pit Type: Separator ☒ Dehydrator ☐ Other ☐		
Land Type: BLM ☒ State ☐ Fee ☐ Other ☐		
Pit Location: (Attach diagram)	Pit dimensions: length <u>10 FT</u> , width <u>10 FT</u> , depth <u>6 FT</u>	
	Reference: wellhead ☒ other ☐	
	Footage from reference: <u>90 FT</u>	
	Direction from reference: <u>50</u> Degrees ☐ East North ☒ of ☒ West South ☐	
Depth To Ground Water: (Vertical distance from contaminants to seasonal high water elevation of ground water)	Less than 50 feet (20 points) 50 feet to 99 feet (10 points) Greater than 100 feet (0 Points) <u>0</u>	
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)	Yes (20 points) No (0 points) <u>0</u>	
Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)	Less than 200 feet (20 points) 200 feet to 1000 feet (10 points) <u>20</u> Greater than 1000 feet (0 points)	
RANKING SCORE (TOTAL POINTS):		<u>20</u>

Date Remediation Started: 8-16-95 Date completed: 8-16-95

Remediation Method: Excavation ☒ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____

other replaced to the excavation pit

Remediation location: Onsite _____ Offsite _____
(ie. landfarmed onsite, name and location of offsite facility)

General Description of Remedial Action: Fiberglass tub and secondary liner were removed, excavation was pursued to a depth of 8 feet, no contamination was visibly evident, the pit was backfilled, the secondary liner and tub were replaced.

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit:
Closure Sampling:
(if multiple samples, attach sample results and diagram of sample locations and depths)

Sample location bottom of excavation

Sample depth 8 feet

Sample date 8/16/95 Sample time UNKNOWN

Sample Results

Benzene (ppm) _____

Total BTEX (ppm) _____

Field headspace (ppm) _____

TPH 25 mg/kg

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)



I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 12/17/96

SIGNATURE J. Vierzbički

PRINTED NAME Jenelle L. Vierzbički
AND TITLE Environmental + Safety Specialist

Marathon Oil Company
La Plata Field
Ohio "F" Government #1A




Client:	Marathon Oil	Project #:	95047
Sample ID:	Ohio 'F' Govt. 1A @ 8'	Date Reported:	08-18-95
Laboratory Number:	8811	Date Sampled:	08-16-95
Chain of Custody No:	4345	Date Received:	08-17-95
Sample Matrix:	Soil	Date Extracted:	08-17-95
Preservative:	Cool	Date Analyzed:	08-18-95
Condition:	Cool and Intact	Analysis Needed:	TPH


Parameter	Concentration (mg/kg)	Det. Limit (mg/kg)
Total Petroleum Hydrocarbons	25	10

ND = Parameter not detected at the stated detection limit.

References: Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water and Waste, USEPA Storet No. 4551, 1978.

Comments:


Analyst


Review