

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐  
well well
2. NAME OF OPERATOR  
Energetics, Inc.
3. ADDRESS OF OPERATOR 80112  
102 Inverness Terrace East, Englewood, CO
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 550FNL & 1880 FEL  
AT TOP PROD. INTERVAL: Same  
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: |                          | SUBSEQUENT REPORT OF: |                                     |
|--------------------------|--------------------------|-----------------------|-------------------------------------|
| TEST WATER SHUT-OFF      | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| FRACTURE TREAT           | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| SHOOT OR ACIDIZE         | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| REPAIR WELL              | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| PULL OR ALTER CASING     | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| MULTIPLE COMPLETE        | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| CHANGE ZONES             | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| ABANDON*                 | <input type="checkbox"/> |                       | <input checked="" type="checkbox"/> |
| (other)                  | <input type="checkbox"/> |                       | <input type="checkbox"/>            |

5. LEASE M <sup>00</sup> NOO-C-1420-1716	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME Mountain Ute	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME Ute 18	
9. WELL NO. 31	
10. FIELD OR WILDCAT NAME Verde Gallup	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 18, T31N, 14W	
12. COUNTY OR PARISH San Juan	13. STATE New Mexico
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 5941 GL	

(NOTE: Report results of multiple completion tests, change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

6-9-80: Rig up mast pole. Perforate 100' with 2 jets. 6-18-80: MIRUPU Farmington Well Service. Run 69 joints 2 3/8" tubing and tag liner at 2402'. Unable to penetrate liner. Spot 40 sacks class "B" cement plug from 2402-2202'. Lay down tubing. Load hole with water. Cement 5 1/2" casing and 5 1/2" x 8 5/8" annulus with 30 sacks class "B". Circulate estimate 2 barrels cement. Install dry hole marker. 6-24-80: Clean up location. Plugged and abandoned.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_

Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Jack D. Cook TITLE Agent DATE 8-28-80  
(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY  
DURANGO, COLO.