5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR	SF 078096
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🔯	Mudge 63-33 8 488
well well to other	9. WELL NO.
2. NAME OF OPERATOR	13 A \$\frac{1}{2} \text{\$\frac{1}{2}\$} \text{\$\frac{1}{2}\$}
EL PASO NATURAL GAS COMPANY	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco MV
P.O. BOX 289, FARMINGTON, NEW MEXICO 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 20, T-31-N, R-11-W,
below.)	N.M.P.M.
AT SURFACE: 1620' S, 1080' E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	Transition
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6116 G. I.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
FRACTURE TREAT \(\sum \) \(\overline{\chi} \) \(\overline{\chi} \) \(\overline{\chi} \)	등 기 등 일반을 되었다.
REPAIR WELL	<u> </u>
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
MULTIPLE COMPLETE	
CHANGE ZONES 🗍 🗍	그 그 그 이 사람들은 중에 가는 사람들이 하는 것이 되었다.
ABANDON*	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	
including estimated date of starting any proposed work. If well is di	rectionally drilled give subsurface locations and
measured and true vertical depths for all markers and zones pertinent	t to this work.)*
	· · · · · · · · · · · · · · · · · · ·
5-17-79: TD 3032'. Ran 85 jts. 7", 20#, K-5	55 intermediate casing, 3020'
set at 3032'. Cemented w/461 cu.ft. cement.	
Top of cement 1400'.	BITTHE SIMILAR
•	· · · · · · · · · · · · · · · · · · ·
5-21-79: TD 5426'. Ran 80 jts 4 1/2", 10.5#	*. K-55 casing liner. 2534' set
2892-5426'. Float collar set at 5409'. Ceme	ented w/439 cu.ft. cement.
WOC 18 hrs.	
	5 B 5 2 6 6 5 8 8 9 1 1
•	
	Table 1 Parts
Subsurface Safety Valve: Manu. and Type	Se @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED D. Dilling Cley	rk DATE 5-31-79
(This space for Federal or State office	ce use) jaka jaka jaka jaka jaka jaka jaka jak
APPROVED BY TITLE	DATE DATE
CONDITIONS OF APPROVAL, IF ANY:	선생님 그 전 기가 가장 그
	Situalia Situalia Constituti Situalia Situalia Situalia Situalia