

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well ☐ gas well ☐ other ☐

2. NAME OF OPERATOR
Energetics, Inc.

3. ADDRESS OF OPERATOR
102 Inverness Terrace East, Englewood, CO 801

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 640' FSL & 1650' FWL
AT TOP PROD. INTERVAL: same
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☒ OIL CON. DIV.

5. LEASE 1700
N00-C-1420-1718

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Mountain Ute

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Ute 12

9. WELL NO.
24

10. FIELD OR WILDCAT NAME
Verde Gallup

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA
Sec 12, T31N, R15W

12. COUNTY OR PARISH San Juan 13. STATE NEW Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6035 GL

NOTE: Report results of multiple completion or zone change on Form 9-330.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-9-80: Rig up mast pole. Perforate at 100' with 2 jets. 6-12-80 MIRUPU-Farmington Well Service. Ran 76 joints 2 3/8" tubing to 2305'. Trip out hole. Dump 3400# 20-40 mesh sand. Trip in hole with tubing and tag sand fill at 2122'. Spot 40 sacks class "B" cement plug from 2112-1912'. Lay down tubing. Load hole with water. Cement 5 1/2" & 8 5/8" x 5 1/2" annulus with 30 sacks class "B" cement. Circulate estimate 3 barrels. 6-18-80 Install dry hole marker. 6-24-80 Clean up location. Well plugged and abandoned.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Jack D. Cook TITLE Agent DATE 8-28-80

(This space for Federal or State office use)

APPROVED BY David J. Miller TITLE Area Manager DATE FEB 24 1984

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.