

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR
Energetics, Inc.

3. ADDRESS OF OPERATOR
102 Inverness Terrace East, Englewood, Colo 80112

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2100'/N & 1940'/E
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input checked="" type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) <input type="checkbox"/>	<input type="checkbox"/>

5. LEASE
Noo-C-1420-1719

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Mountain Ute

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Ute 13

9. WELL NO.
32

10. FIELD OR WILDCAT NAME
Verde Gallup

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
13-T31N-R15W

12. COUNTY OR PARISH
San Juan

13. STATE
NM


14. API NO.

15. ELEVATIONS (SHOW DF, KDB AND WD)
5640 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drill 7 7/8" hole to 2147' and ran IES log to correlate. Ran 52 joints 5 1/2" 14 lb casing and landed at 2146'. Cemented with 75 sk Class "B" cement with 1/4 lb Celorlake/sk Good circulation through job with plug down at 0815 hour 1-20-79. Now waiting on completion unit.



Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED John Alexander TITLE Agent DATE 3-1-79

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAR 7 1979

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.