UNITED STATES DEPARTMENT OF THE INTERIOR

| UNITED STATES | 5. LEASE විසිදුවූ පි පුස් 3 |
|--|--|
| DEPARTMENT OF THE INTERIOR | Noo-C-1420-1719 = * 55 |
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| | Mountain Ute & & 457 |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAME: 18 of |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | discrete dis |
| reservoir. Use Form 9-331-C for such proposals.) | 8. FARM OR LEASE NAME के उत्त है। Ute 13 उद्देश के देखें |
| 1. oil gas other | 9. WELL NO. 2 2 3 3 5 5 6 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 8 7 |
| | 9. WELL NO. 2 15 15 15 15 15 15 15 15 15 15 15 15 15 |
| 2. NAME OF OPERATOR Energetics, Inc. | 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS OF OPERATOR | 10. FIELD OR WILDCAT NAME Verde Gallup: |
| | 1 21. SEC., T., R., M., OR BLK. AND SURVEY OR |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 | AREA 현실 및 변환경을 |
| below.) | 13-T31N-R15W 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| AT SURFACE: 2100'/N & 1940'/E | 12. COUNTY OR PARISH 13. STATE |
| AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same | San Juan NM 3 |
| Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, | 14. API NO. 5 (200) # 0.55 (4) # 0.55 (4) |
| REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| , <u> </u> | 5640 GL 😤 😤 🖟 💆 🗸 💆 🗸 |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | 9848 3 3 4 4 4 |
| TEST WATER SHUT-OFF TEST WATER SHUT-OFF | |
| FRACTURE TREAT US SHOOT OR ACIDIZE US | |
| REPAIR WELL | (NOTE: Report results of multiple completion or zone |
| PULL OR ALTER CASING | change on Form 9–330.); (non-2-39) (non-2-2-39) (non-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2- |
| MULTIPLE COMPLETE | 10.1 (a) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c |
| ABANDON* | ifpurit sage it sag |
| (other) | ancitanten anaspollen stagonen och stagonen och stantanten och anten och s och anten och s och anten och s |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state | e all pertinent details, and give pertinent dates, |
| including estimated date of starting any proposed work. If well is d | irectionally drilled, give subsurface locations and |
| measured and true vertical depths for all markers and zones pertiner | |
| Rig up cable tools and penetrate Gallup formation | on from 2147 to 2425. Reached t.d. |
| on 2.21.70 Fractured open hole section with 190 bbl crude oil containing 4100 ib | |
| 10-20 sand. Average rate was 31 bpm at 400 psi with an isip of 0 psi. Cleaned | |
| out sand to t.d. and ran 4" slotted liner to cover open hole area. Ran 2 3/8" tubing with pump and rods and placed well on test. | |
| tubing with pump and rods and placed well on te | st. |
| | |
| مور | |
| | orayo Naggi už 1985 |
| f(x) | |
| | |
| age of the control of | ka ^o 10 % |
| Subsurface Safety Valve: Manu. and Type | |
| i de la companya de | Marie To the state of the state |
| 18. I hereby certify that the foregoing is true and correct | |
| SIGNED JOHN Alexander TITLE Agent | DATE 3-1-79 - 3-1- |
| (This space for Federal or State off | ice use) |
| TITLE | |
| APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY: | DATE OF FILE TO |
| · | |
| | 비탈 기술 원리 원리 원리 원리 원리 시작 기계 |
| en la tantina de Prison | side MAR 7 1979 - |
| *See Instructions on Reverse S | 111/111 |

U. S. GEOLOGICAL SUITHEY DURANGO, COLO.