

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well well
2. NAME OF OPERATOR
Energetics, Inc.
3. ADDRESS OF OPERATOR
102 Inverness Terrace East, Englewood, CO 80111
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2100' FNL & 1940' FEL
AT TOP PROD. INTERVAL: same
AT TOTAL DEPTH: same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

RECEIVED
FEB 28 1984
OIL CON. DIV.
DIST. 3

5. LEASE M00 N00-C-1420-1719
6. IF INDIAN, ALLOTTEE OR TRIBE NAME Mountain Ute
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME Ute 13
9. WELL NO. 32
10. FIELD OR WILDCAT NAME Verde Gallup
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 13, T31N, R15W
12. COUNTY OR PARISH San Juan
13. STATE New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD) 5640 GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-9-80: Rig up mast pole. Perforate 100' with 2 jets. 6-13-80 MIRUPU Farmington Well Service. Ran 76 joints 2 3/8" tubing to 2160'. Pull tubing. Dump 3500# 20-40 mesh sand down casing. Run 2 3/8" tubing. Hit bridge at 700' and 1150'. Wash out same. Tag sand fill at 2070'. Spot 40 sacks class "B" cement plug from 2065-1865'. Lay down tubing. 6-14-80 Load hole with water. Cement 5 1/2" casing and 5 1/2" x 8 5/8" annulus with 30 sacks class "B" Circulate estimate 1 barrel cement. 6-18-80 Install dry hole marker. 6-23-80 Clean up location. Well plugged and abandoned.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Jack D. Cook TITLE Agent DATE 8-28-80

(This space for Federal or State office use)

APPROVED BY David J. Miller TITLE Area Manager DATE FEB 24 1984

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

U.S. GEOLOGICAL SURVEY
DURANGO, COLO.