16 len 38 W6 110133

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	MOUNTAIN UTE
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME 3 days
(Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME ଓ ପ୍ରଥମ
1. oil gas	
well XXX other	
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME 336
ENERGETICS, INC. 3. ADDRESS OF OPERATOR 80112	VERDE GALLUPAS CONTRACTOR
3. ADDRESS OF OPERATOR 80112 102 Inverness Terrace East, Englewood, Colorado	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 솔히딩힐 및 하듬혀LL
below.)	
AT SURFACE: 890'/S, 2000'/W	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: SAME	SAN JUAN E S NEW MEXICO
OATIL	14. API NO. A STATE TO STATE T
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT. OR OTHER DATA	
REPORT, OR OTHER DAM	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5790 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7,800 0 644.0
TEST: WATER SHUT-OFF 🔲 🛗	
FRACTURE TREAT 📙 🖂	y bac you blug blug thoras y too too of
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.) → 😅 🖫 🗁 💆
MULTIPLE COMPLETE	emoitouria oifenego lle efigacia no dimin adi ta noti banado noti blanado noti blan
ABANDON*	Aructis I open If the man Inches I
(other)	The state of the s
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	e all pertinent details, and give pertinent dates.
including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and	
measured and true vertical depths for all markers and zones pertinen	it to tills work.).
Drilled 7 7/8" hole to 1670'. Conducted open hole drill stem test from 1650' to	
1670'. Recovered 30' of drilling mud with no oil or gas shows ? Continued	
drilling to 1825' and ran IES open hole logs. Ran 5 1/2" 14# casing and landed	
at 1824'. Cemented with 75 sk. class "B" cement and 1/4# Flocele/sk: Plug	
down at 2045 hours, 03/29/79. Now waiting on cable tools.	
	edunal
	gailliandu na wol lo auca areall o wolsel a niups i ste au bilge a wospie a
Subsurface Safety Valve: Manu. and Type	C// o. 5 5 5 Set 6 Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED CONTROL TITLE AGENT	DATE fune 20, 19793
(This space for Federal or State offi	ice use)
APPROVED BY THILE	DATE PARTY TO BE SEED
CONDITIONS OF APPROVAL, IF ANY:	\$ 15 9 5 4 4 1 3 2 3 \$
	변경 전 경험 기계
	يسترين والوالية المحاسبة والمحاسبة و