5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

DEFARTMENT OF THE INTERIOR	NOO-C-1420-1419 ★ ₩ ≦ 및
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	Mountain Utes S 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	• 14 6
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME ଓ ପ୍ରତିଶ୍ୱର Ute 13 ଚିଛିନ୍ଦ୍ର ପ୍ରତିଶ୍ୱର
1. oil gas other	
	9. WELL NO. 0 10 1 1 10 10 10 10 10 10 10 10 10 10
2. NAME OF OPERATOR	
Energetics, Inc.	10. FIELD OR WILDCAT NAME Verde Gallup
3. ADDRESS OF OPERATOR 102 Inverness Terrace East, Englewood, Colo 801	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	131. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	13-T31N-R15W 6 9 9 9 9
AT SURFACE: 1930'/S & 410'/E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan Barara NM 2 2 2
AT TOTAL DEPTH:	14. API NO. 항 사람 및 경험을 받
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	Pare Degan
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5763 GL 성용취임 및 및 출동경
TEST WATER SHUT-OFF	20 1
FRACTURE TREAT	to year
SHOOT OR ACIDIZE	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
REPAIR WELL PULL OR ALTER CASING TO THE STATE OF THE	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	change on Form 9-330.)- 1900 200 200 200 200 200 200 200 200 200
CHANGE ZONES	enotinexi eti enotinexi eti enotinexi eti enotine eti
ABANDON*	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is directly measured and true vertical depths for all markers and zones pertinent	rectionally drilled give subsurface locations and
Rig up rotary tools. Spud 12 $\frac{1}{4}$ " hole at 2030 hour	rs 2-3-79. Drill to 94 . Ran
2 joints 8 5/8" casing and set at 92'. Cement wi	그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그
CaCl ² . Good circulation through out job. Plug o	down at 0930 2-4-79. W.O.C.
l2 hours.	
	The section of the se
ميمير	out Suffither to the state of t
• • • • • • • • • • • • • • • • • • • •	IN COMPANY OF SEER
Subsurface Safety Valve: Manu. and Type	CON 3 Set @ - Ft.
18. I hereby certify that the foregoing is true and correct	Mr Dig.
	10 70 F 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
SIGNED CIM WINAWILL TITLE Agent	DATE 2-20-19 25 25 25 25 25 25 25 25 25 25 25 25 25
(This space for Federal or State office	e use) ခ်ဋ္ဌိသည် ဆိုများခဲ့
APPROVED BY TITLE	DATE DATE
CONDITIONS OF APPROVAL, IF ANY:	DETELVEN
• •	
	n in Signature
	: NAR 7 1979 =

*See Instructions on Reverse Side

16.*******