UNITED STATES DEPARTMENT OF THE INTERIOR

| UNITED STATES | 5. LEASE & 5.55 & 5.65 |
|--|---|
| DEPARTMENT OF THE INTERIOR | Noo-C01420-1719 = % € 5 |
| | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| GEOLOGICAL SURVEY | Mountain Ute 8 8 2 8 4 |
| `````````````````````````````````````` | - C - A A A A |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAMES |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | |
| reservoir. Use Form 9–331–C for such proposals.) | 8. FARM OR LEASE NAME 9 0 11 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 |
| 1. oil 🖂 gas 🗇 | |
| well well other | 9. WELL NO. 22 10 10 10 10 10 10 10 10 10 10 10 10 10 |
| 2. NAME OF OPERATOR | 43 異型性点 |
| Energetics, Inc. | 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS OF OPERATOR | 10. FIELD OR WILDCAT NAME 기계 |
| 102 Inverness Terrace East, Englewood, Colo. 801 | 11. SEC. T. R. M. OR BLK AND SURVEY OR |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 | |
| below.) | AREA = = = = = = = = = = = = = = = = = = = |
| AT SURFACE: 1870'/S & 1715'/W | 12. COUNTY OR PARISH 13. STATE |
| AT TOP PROD. INTERVAL: Same | San Juan San San SMESSE |
| AT TOTAL DEPTH: Same | |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. | 1 2 3 2 3 6 7 |
| REPORT, OR OTHER DATA | <u> </u> |
| HEI ONI, ON OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | 5773 GL ខែ 🖟 🖟 ដីគឺ៩ |
| TEST WATER SHUT-OFF TO TO THE TOTAL | riogat bri datë yas de bluo de |
| FRACTURE TREAT | 00000000000000000000000000000000000000 |
| SHOOT OR ACIDIZE | Sugar Officers Officers |
| REPAIR WELL | (NOTE: Report results of multiple completion or zone |
| PULL OR ALTER CASING [| change on rorm 9=330.75 12 G E 2 |
| MULTIPLE COMPLETE | in the second se |
| CHANGE ZONES | oitourt |
| ABANDON* | tructions and the control of the con |
| (other) | enoithurten citation leverations cotton of the cotton of t |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, | |
| including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and | |
| measured and true vertical depths for all markers and zones pertinen | it to this work.)* 월골몰동 - 월 월달골존 |
| Drill 7 7/8" hole to 2121' and run IES open hole | log to correlate. Continue drilling |
| to 2275'. Ran 56 joints $5\frac{1}{2}$ " 14 lb casing and lar | nded at 2275 Cemented with 75 sacks |
| Class "B" + 1 lb Celo flalce/sk. Had only partial circulation through job. Plug | |
| down 1930 hours -2-2-79. | 410 100 100 100 100 100 100 100 |
| | 그 그 그 그 그는 그는 중인 책과 본 그 그런 그 한 중 밖값 |
| and the second s | cooping gnithlandus (blugs) bas with tensify the with tensify the with the status of the cooping and the cooping and the cooping to the cooping and the cooping to the coop |
| | |
| | |
| | |
| | " GY JONE STEEL OF THE FETT |
| | |
| | 10 25 8 3 2 1 3 2 1 3 2 5 8 3 3 3 5 8 3 3 3 3 3 3 3 3 3 3 3 3 3 |
| | 7/ 02. March 65 6194 |
| | not benging the state of the st |
| Subsurface Safety Valve: Manu. and Type | And the state of t |
| 18. I hereby certify that the foregoing is true and correct | Indue not benerote at implications and benerote of the first of the section of th |
| $H = C \cdot A \cdot L \cdot A$ | 10 1 10 1 10 1 10 1 10 1 10 1 10 1 10 |
| SIGNED John William TITLE Agent | DATE |
| | |
| | |
| APPROVED BY TITLE | DATE |
| CONDITIONS OF APPROVAL, IF ANY: | າອກອວ ໃດຄວາມ ຂອງແປດ ອີກ າຍ. ອີກ າຍ. ອີກ ເຄດປີນ ອີກເຄດປີ |
| | ກອກອນ ການ |
| | District Control of the Control of t |
| | oration and the second |
| *See Instructions on Payarce C | ida i |