UNITED STATES

	roini Approved.			
Ģŧ	Budget	Bureau	No.	42-R1424

DEPARTMENT OF THE INTERIOR	NM 013688 전 기
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
reservoir, use rotti 3-331-C for such proposals.)	8. FARM OR LEASE NAME 및 요즘을 Atlantic 하게 없는 및 모든 및 모
1. oil gas 🖂 other	
2. NAME OF OPERATOR	·
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Blanco P.C. Ext
P.O. Box 289, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 24, T-31-N, R-10-W
below.)	N.M.P.M. ■ ♣ ♣ ₹
AT SURFACE: 810'N, 1440'E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico
	14. API NO. 25 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	<u> </u>
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	6608' G.L.한국 및 분분증공
TEST WATER SHUT-OFF \(\Bar{\chi} \)	
FRACTURE TREAT	400 d to 400
SHOOT OR ACIDIZE	7 (20 0) 10 (10
REPAIR WELL	(NOTE: Report results of multiple completion or zone
MULTIPLE COMPLETE	change on Form 9-330.70 in only 518 que to the first of multiple completion or zone change on Form 9-330.70 in only 518 que to the first of the firs
CHANGE ZONES	toilbutt sysqe fla qape to man sit i ni bama a naibal
ABANDON*	Sitourita nage fla sacroto en sitro l'benuar l'bernari dit ene dit ene
(other)	encifountan encifountan enciforment of the enciforment of the enciforment of the enciforment of the enciforment of the enciforment of the of the enciforment of the of th
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertinent.	irectionally drilled, give subsurface locations and
7-5-79: Spudded well. Drilled surface hole	. Ran 3 joints $8.5/8!!$ $24 # ?$
K-55 surface casing 135' set at 147	
cement. Circulated to surface. WO	
minutes.	0 8 m o o o o o o o o o o o o o o o o o o
•	n o o o o o o o o o o o o o o o o o o o
Г _Б	on a book of the second of the
Į R.	ECEIVE ANTENNA PROPERTY OF THE
·	JUL 1 1979 in both of the first
of the second o	JUL 11 1970 28 8 8 8 8 8 90 00 00 00 1978
{	
U. S.	GEOLOGICAL SHOWEY STATE OF THE
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	800 E0 93 6 KB W
SIGNED SIGNED TITLE Drilling Cle	rk pare July 97 1979 2 3 3
SIGNED - TITLE DITTING CITE	TK DATE <u>JULY, 97 1979 등 연단</u>
(This space for Federal or State offi	
APPROVED BY TITLE	DATE THE RESERVE TO THE PARTY OF THE PARTY O
CONDITIONS OF APPROVAL, IF ANY:	
	tenses
	most mestal another most most most most most most most most
- *See Instructions on Reverse S	