DE

IIIITED ATITES	⊕ Budget Bureau No. 42–R1
UNITED STATES	5. LEASE 22 2 2 3 3 4 4
PARTMENT OF THE INTERIOR	NMU13688 \$ \$ 25
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	하늘받아 쓴 있습니?

	-
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different	무취들이 공연 원통
reservoir. Use Form 9–331–C for such proposats.)	8. FARM OR LEASE NAME
1. oil gas 🖂	Atlantic : Add F
well well other	9. WELL NO.
2. NAME OF OPERATOR	ា 16 មីនិទ្ធ 🖟 🐧 🐧
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco PG
P.O. Box 289, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA Sec. 24, T-31-N, R-10-W
below.)	N.M.P.M.
AT SURFACE: 1470'S, 1280'E	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NU.
REPORT, OR OTHER DATA	
V V	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6578' G.L.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	03/0 U.L.
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	·
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING [change on Form 9–330.)
MULTIPLE COMPLETE CHANGE ZONES	
ABANDON*	그 그 그 그 얼룩하는 그는 말병을 하는 때
(other)	그 그 그 이 이 그 중요한다는 그는 중에 없는 그는 그는 그는 그는 그를 살았다.
	그 그는 그는 이 그 회장살회 그 수 그 의록생하는 빛
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	te all pertinent details, and give pertinent dates,
including estimated date of starting any proposed work. If well is c measured and true vertical depths for all markers and zones pertined	directionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertine	int to this work.)
7-15-79: T.D. 3525'. Ran 109 joints. 2 7/8"	
	, 6.4#, J-55 production casing,3515'
	Cemented with 600 cu. ft. cement.
WOC 18 hours. Top of cement at 2000	
garage, p. cost of	SENTENSIS OF THE SERVICE OF THE SERV
	CEIVED
11	IL 20 1979
30	
U. S. G	EOLOGICAL SURVEY TO THE TOTAL STATE OF THE SURVEY OF THE S
i Eval	THE PROPERTY OF STATE OF THE PARTY OF THE PA
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	
SIGNED A GUSEO TITLE Drilling Cle	rk DATE July 18, 1979

(This space for Federal or State office use)

DATE

