ALA.

## UNITED STATES

	9,		Budget	Bureau	No. 42-R142
LEASE	16	Ç	23.50	C-	34 2 3

DEPARTMENT OF THE INTERIOR	USA SF 079353
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
CUMPRY NOTICES AND DEPORTS ON WELLS	7. UNIT AGREEMENT NAME-
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different	○ ▶
(Do not use this form for proposals to drill or to deepen or plug back to a differen reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas to other	San Juan 32-8 Unit
Well street	9. WELL NO. 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
2. NAME OF OPERATOR  Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME.
3. ADDRESS OF OPERATOR	Blanco Mesa Verde
P.O. Box 90, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	
below.) at surface: 840' FWL & 960' FSL	Sec 33 T32N R8W
AT SURFACE: 840' FWL & 900' FSL AT TOP PROD. INTERVAL: Same	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH: Same	San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
DECUECT FOR APPROVAL TO. CURCEOUTAIT DEPORT OF	6502 'GR 💆 🖔 💆 💆 🕺
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF	
FRACTURE TREAT	an bon Cyns Sour 9 Sour 9 Sour 9 Sour 9 Sour 9 Sour 9 Sour 9 Sour 9 Sour 9
SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.) ම වැඩි ව
MULTIPLE COMPLETE	change on Form 9–330.); Rock 1995 (2015)
CHANGE ZONES	
ABANDON* (other) 'Drilling & Completion Operations'	PAGE TWO OF TWO 2 2 2 5 5 5
Λ	10 10 10 10 10 10 10 10 10 10 10 10 10 1
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stational including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and ent to this work.)*
2-14-79 TIH w/ 3-7/8" bit & cleaned out to PBTD	
Spotted 500 gal $7\frac{1}{2}\%$ HCl. Perfed 25 hole	es from 5470' to 5838' Fraced w/
100,000# 20/40 sand in frac fluid contai	ning FR-20. Total fluid = 2561 bbls
Job complete @ 2200 hrs. MIR = 46 BPM, AIP = 2250 psi. ISIP = 100 psi, 5 min =	AIR = 44 BPM; MIP = 2400 psi;
2-16-79 Gauged well thru annulus @ 1236 MCFD. R	an 189 its of 2-3/8" $4.7 \pm 3$ -55.
EUE tbg landed @ 5850'. Pumped out exp	pendable check. Released rig.
2-17-79 Blew well & SI for IP Test.	
(Note: Due to squeeze job, no temp surv	vey run on 4-1/21 casing liner.)
	100 mg
Subsurface Safety Valve: Manu. and Type	
	다 하는 다 하는 다 한 다 하는 다 한 다 하는 다 하는 다 하는 다
18. I hereby certify that the foregoing is true and correct	부 닭 링워 있는 그 것 같은 요. []
SIGNED Barbara C. Key TITLE Production	Clerk DATE 12-20-79.
(This space for Federal or State of	office use)
APPROVED BY TITLE	DATE TPPEPTE
CONDITIONS OF APPROVAL, IF ANY:	
NMOCC	1
	SHE AND USE
*See Instructions on Reverse	e Side FARMINGTON DISTAIST