

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYForm Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other2. NAME OF OPERATOR
Northwest Pipeline Corporation3. ADDRESS OF OPERATOR
P.O. Box 90, Farmington, New Mexico 874014. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1670' FNL & 800' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐CHANGE ZONES ☐ABANDON* ☐

(other) 'Drilling Operations' X

5. LEASE

USA SF 078460

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

San Juan 32-7 Unit

8. FARM OR LEASE NAME

San Juan 32-7 Unit

9. WELL NO.

56

10. FIELD OR WILDCAT NAME

Basin Dakota

11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA

Sec 17 T32N R7W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

14. API NO.

30-045-23686

15. ELEVATIONS (SHOW DF, KDB, AND WD)

6333' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1-30-80 Spudded 12-1/4" surface hole @ 2345 hrs.

2-1-80 Drld to 359'. Ran 8 jts of 9-5/8", 36#, K-55, ST&C csg set @ 353' KB. Cmted w/ 275 sks Cl'B' w/ 3% CaCl2. Circ out 3 bbls cmt. Plug down @ 0200 hrs.

2-4-80 Drld 8-3/4" hole to 3610'. Ran 92 jts of 7", 20#, K-55, ST&C csg set @ 3610'. Cmted w/ 125 sks Cl'B' 65/35 poz w/ 12% gel. Tailed w/ 50 sks Cl'B' w/ 2% CaCl2. Plug displaced w/ 147 bbls & down @ 2100 hrs. WOC. Ran temp survey & found top of cmt @ 1900', PBTD @ 3560'. WOC. Pr tested @ 1900' sig, OK.

2-5-80 Started drlg 6-1/4" hole.

2-8-80 Drld to TD @ 7890' KB. Ran IL/GR & CDL/GR logs.

2-10-80 Ran 238 jts of 4-1/2", 11.6# & 10.5#, K-55, ST&C csg set @ 7875' KB. Cmted w/ 250 sks Cl'B' w/ 8% gel & 12-1/4# fine gilsonite/sk, & 0.4% HR4 (preceded w/ 40 bbls cmt). Plug down @ 0430 hrs. WOC. Top of cmt by temp survey @ 7860' Ft.

Subsurface Safety Valve: Manu. and Type

NOW WAITING ON COMPLETION.

18. I hereby certify that the foregoing is true and correct

SIGNED Barbara C. Rex TITLE Production Clerk DATE 2-20-80

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE DATE

MAR 3 '80

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.