UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9-331 Dec. 1973 UNITED STATES	Form Approved. Budget Bureau No. 42-R1424
DEPARTMENT OF THE INTERIOR	5. LEASE
GEOLOGICAL SURVEY	SF 078097 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form $9-331-C$ for such proposals.)	8. FARM OR LEASE NAME
1. oil gas G	Heaton
well well other	9. WELL NO.
2. NAME OF OPERATOR	1A
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Mesa Verde
Box 289, Farmington, New Mexico 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1830'S, 1100'E	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T-31-N, R-11-W N.M.P.M.
AT SURFACE:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan_ New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	,
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5904' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	-
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone 2) change on Form 9-330.)

gas well well other 2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1830'S, 1100'E AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES S. GEDLUGIONE SURVE ABANDON* FARMINGTON, N. M. (other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PBTD 5246'. Tested casing to 3500#, OK. Perfed 4677,4683,4759,4780,4786,4792, 1-23-80: 4816,4822,4832,4838,4844,4850,4864,4872,4882,4903,4908,4958,4973,4983,4993,5008, 5014,5034,5043,5072,5082' w/1 SPZ. Fraced w/68,500# 20/40 sand, 177,000 gal. wtr. Flushed w/6200 gal. wtr.

Subsurface Safety Valve: Manu. and Type ____ Set @ 18. I hereby certify that the foregoing is true and correct TITLE _Drilling Clerk DATE _January SIGNED

(This space for Federal or State office use)

APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:

DATE

FARMINGTON CIGHNOT , Y

*See Instructions on Reverse Side