## HAUTED STATES

DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	5. LEASE SF 078097 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME		
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different			
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME		
1. oil gas X other	Heaton		
Well Well Other	9. WELL NO.		
2. NAME OF OPERATOR El Paso Natural Gas Company	4A  10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 87401	Blanco Mesa Verde 11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 29, T-31-N, R-11-N N.M.P.M.		
AT SURFACE: 1825'S, 930'E	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL:	San Juan New Mexico		
AT TOTAL DEPTH:  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
	5980,' GL		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF U			
FRACTURE TREAT	<u> </u>		
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)		
MULTIPLE COMPLETE			
(other)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1-1-80: Spudded well. Drilled surface hole.

Ran 5 joints 9 5/8", 36#, KS surface casing 204' set at 217'. Cemented w/224 cu. ft. cement. Circulated to surface. WOC 12 hours; held 600#/30 minutes.

Subsurface Safety Valve: Manu. and Type				Set @	Ft.
18. I hereby certify that the foregoing is tru	ue and correc	bt Drilling	Clerk DATE	January 3,	1979
	(This space fo	r Federal or State	office use)		
APPROVED BY	TITLE		4	<b>y</b> 31	Tea lite

\*See Instructions on Reverse Side

