UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

m 9–331 c. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF-077651
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON	
not use this form for proposals to drill or to deepen or plug back to a different ervoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
oil gas X other	Richardson
Well Well Other NAME OF OPERATOR	9. WELL NO 7-E
Southland Royalty Company	10. FIELD OR WILDCAT NAME
ADDRESS OF OPERATOR	Basin Dakota -
P. O. Drawer 570, Farmington, New I LOCATION OF WELL (REPORT LOCATION CLEARLY.	
helow)	Section 15-T31N-R12W
AT SURFACE: 1520' FNL & 950' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
CHECK APPROPRIATE BOX TO INDICATE NATURE	OF NOTICE,
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
_	6230' GR
QUEST FOR APPROVAL TO: SUBSEQUENT RE	PORT OF:
ST WATER SHUT-OFF	
ACTURE TREAT U U OOT OR ACIDIZE D	
PAIR WELL	(NOTE: Report results of multiple completion or zone
LL OR ALTER CASING 🔲	change on Form 9-330.)
ILTIPLE COMPLETE	
ANGE ZONES ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	
her) Spud and Casing Report	
nein jud und odsing neporo	· ··
 DESCRIBE PROPOSED OR COMPLETED OPERATION including estimated date of starting any proposed we measured and true vertical depths for all markers and 	S (Clearly state all pertinent details, and give pertinent dates, ork. If well is directionally drilled, give subsurface locations and a zones pertinent to this work.)*
11-06-79 Spudded 12-1/4" surface	ce hole at 2:00 P. M. 11-06-79 and

(Do not use this form for proposals to drill or to deepen or plug back to a different				
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME			
1. oil gas gy	Richardson			
well well other	9. WELL NO			
2. NAME OF OPERATOR	/ -E			
Southland Royalty Company	10. FIELD OR WILDCAT NAME			
3. ADDRESS OF OPERATOR	Basin Dakota			
P. O. Drawer 570, Farmington, New Mexico	11. SEC., T., R., M., OR BLK. AND SURVEY OF			
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA			
helow)	Section 15-T31N-R12W			
AT SURFACE: 1520' FNL & 950' FEL	12. COUNTY OR PARISH 13. STATE			
AT TOP PROD. INTERVAL:	San Juan New Mexico			
AT TOTAL DEPTH:	14. API NO.			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,				
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD			
	6230' GR			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:				
TEST WATER SHUT-OFF				
FRACTURE TREAT				
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone			
PULL OR ALTER CASING	change on Form 9–330.)			
MULTIPLE COMPLETE				
CHANGE ZONES				
ABANDON*				
(other) Spud and Casing Report	- ·			

Spudded 12-1/4" surface hole 11-06-79 drilled to a TD of 220'. Set 5 joints (188') of 9-5/8", 36#, K-55 casing at 200'. Cemented with 125 sacks Class "B" neat with 3% CaCl2. Plug down at 6:30 P.M. 11-06-79. Cement circulated to surface.

Subsurface Safety Valve:	Мапи.	and	Type
--------------------------	-------	-----	------

19. I hareby certify that the fore	akina ik	+ 10/10	hace	correct

November 7, 1979 TITLE Dist. Prod. Mgr __ DATE _ SIGNED (This space for Federal or State office use)

_ TITLE

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side