

District I

P.O. Box 960, Hobbs, NM

District II

P.O. Drawer DD, Artesia, NM 88211

District III

1000 Rio Bruzos Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources DepartmentOIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO

APPROPRIATE

DISTRICT OFFICE

AND 1 COPY TO

DEPUTY OIL & GAS INSPECTOR

MAR 28 1995

Approved

PIT REMEDIATION AND CLOSURE REPORT

Operator: Phillips Petroleum Company Telephone: 505-599-3400Address: 5525 Hwy. 64, NBU 3004, Farmington, NM 87401Facility Or: San Juan 32-7 Unit #55Well Name KLocation: Unit or Qtr/Qtr Sec NE SW Sec 7 T 32N R 7W County San JuanPit Type: Separator X Dehydrator Other Land Type: BLM State Fee X Other RECEIVED
FEB - 8 1995
OIL CON. DIV.
DIST. 3Pit Location: Pit dimensions: Length 25' width 25' depth 3'
(Attach diagram)Reference: wellhead X other Footage from reference: 40Direction from reference: 90 Degrees East North XX of West South Depth to Ground Water: ? assume <50
(vertical distance from
contaminants to seasonal
highwater elevation of
ground water)

Less than 50 feet	(20 points)	
50 ft to 99 feet	(10 points)	
Greater than 100 feet	(0 points)	<u>20</u>

Wellhead Protection Area:
(less than 200 feet from a private
domestic water source, or: less than
1000 feet from all other water sources).

<u> </u>	Yes	(20 points)	
<u>X</u>	No	(0 points)	<u>0</u>

Distance to Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches.)

<u> </u>	Less than 200 feet	(20 points)	
<u> </u>	200 feet to 1000 feet	(10 points)	
<u>X</u>	Greater than 1000 feet	(0 points)	<u>0</u>

PITCFRM.WK3

RANKING SCORE (TOTAL POINTS): 20

Date Remediation Started: N/A Dated Completed: _____

Excavation _____ Approx. cubic yards _____

Landfarmed _____ Insitu Bioremediation _____

Other _____

Remediation Method: Onsite _____ Offsite _____
(Check all appropriate sections)

General Description of Remedial Action: N/A

Initial assessment of pit shows soil to be clean at the surface
and 3' below pit bottom.

Ground Water Encountered: No X Yes _____ Depth _____

Final Pit: Sample location deepest part of pit. Sampled with a backhoe.

Closure Sampling:
(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

Sample depth 3' below pit bottom

Sample date 7-6-94 Sample time _____

Sample Results

Benzene (ppm) _____

Total BTEX (PPM) _____

Field Headspace (ppm) 2

TPH 24

Ground Water Sample: Yes _____ No X (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETED TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE 2/1/95 PRINTED NAME Ed Hasely

SIGNATURE Ed Hasely and TITLE Environmental Engineer

PHILLIPS PETROLEUM PIT ASSESSMENT/RE-ASSESSMENT SUMMARY
REVISED DATE JULY 14, 1994

1994

ENVIROTECH, INC.

PIT NO.	WELL NAME	U-S-T-R	PIT TYPE	RANK SCORE	CLOSURE STANDARD (PPM)	DATE	GRADUATED ENCOUNTERED Sub-Surf Depth	SOIL TYPE	SAMPLE NO.	Organic Vapor Meter (PPM)	Total Recoverable Per. Hydro. (PPM)	EPA METHOD 8020 (PPB)					TOTAL BTEX	STATUS	
												METHOD 5030 PURGE-AND-TRAP							
												Benzene	Toluene	Ethyl Benzene	Xylene				
PA203	SAN JUAN 32-7, #62 DK	M273207	SEP	10	1000	6-23-94	NO	MC	T1-5	451									
									T1-6	191	534			0	119	890	7610	8789	CLOSE
									T1-9	32									
									T2-8	0									
PA204	SAN JUAN 32-7, #63 DK	G263207	SEP	0	5000	6-23-94	NO	CM	T1-4	280	>11000								REM ~ 4'
									T2-2.5	8	66								
PA205	SAN JUAN 32-7, #65	K073207	SEP	0	5000	7-6-94	NO	SC	T1-3	3	24								CLOSE
									T1-6	2									
PA206	SAN JUAN 32-7, #3	A163207	PROD	0	5000	7-6-94	NO	CP	T1-3	1	10								CLOSE
									T1-6	1									
PA207	SAN JUAN 32-7, #11	H203207	SEP	10	1000	7-6-94	NO	SP	T1-4	0	12								CLOSE
									T1-7	1									
PA208	SAN JUAN 32-7, #157 DK	I173207	SEP	0	5000	7-6-94	NO	SP	T1-5	86	5440								REM ~ 5'
									T2-3	89	982								
PA209	SAN JUAN 32-7, #60 DK	A203207	SEP	0	5000	7-6-94	NO	SP	T1-5	139	33000								REM ~ 5'

