DEPARTMENT (	) STATES DF THE INTERIOR ID MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY NOTICES AN		5. Lesse Designation and Sarial No.
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		SF-078051
	PERMIT - " for such proposals	8. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well		
Oil Gee Other		8. Well Name and No.
2. Name of Operator	Attention:	Neal #2
Amoco Production Company	Gail M. Jefferson, Rm 1295C	8. API Well No.
3. Address and Telephone No.		3004523950
P.O. Box 800, Denver, Colorado 80201	(303) 830-6157	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Basin Dakota/Mesaverde
830'FSL 1085FWL	60. 4 T 31N R 11W Unit M	11. County or Parish, State
		San Juan New Mexico
12. CHECK APPROPRIATE BOX(s	) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
	Plugging Back	New Construction Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	(Note: Re	_i Dispose Water port results of multiple completion on Well Completion or tion Report and Log form. )
If you have any technical questions please administrative questions.	contact Khanh Vu at (303) 830-4920 or myse	<u> </u>
	UN - 5 183 OIL CON. D DIST. 3	
14. I hereby certify the forenoing is true and correct Signed	DUST: 3           m           Title           Title	ACCEPTED FOR RECORD
Signed Level U. Herse (This space for Federal or State office use) Approved by	DUST: 3           m           Title           Title	ACCEPTED FOR RECORD

. •

Neal 2 - Well Repair - Subsequent

Set .

MIRUSU 3/24/95. TOH w/2 3/8" tbg.

Ran CCL and GR to correlate fill and plug back total depth from 6900'-7582' to drill out Lower Dakota.

TIH with tbg and set RBP @ 5550' in order to run CBL and TMD log. Pressure tested casing to 1000#. Held ok.

Ran Thermal Multigate Decay Log and CBL, CCL and GR from 3330-5515'. Est top on 4.5" casing @ 3900'.

TIH w/tbg and removed RBP @ 5550'. TIH w/bit and tbg and drilled out float collar junk and cmt to 7590'.

Perforated from 7572-7584' w/2 jspf, .340 inch diameter, a total of 24 shots fired.

TIH w/3.875" tapered mill to clean out tight spots @ 7337' and 7313-16'. Unable to make any hole @ 7315'. Spent 2 hrs in one spot. Other tight spot @ 7442'. Unable to get PKR in hole to 7555'.

Landed tbg and rigged up to swab to IFL @ 6000'. Made 9 runs, rec. 12 bbls wtr. Well started to flow. Flowed well for 2 hrs on 2 inch open choke.

TIH and land production string @ 7545'. SICP 400#, SITP 250#.

RDMOSU 4/4/95.