

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	3004524042
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Thurston Com A
2. Name of Operator Amoco Production Company	8. Well No. 1
3. Address of Operator P.O. Box 800 Denver Colorado 80201 (303) 830-5129	9. Pool name or Wildcat Basin Dakota
4. Well Location Unit Letter <u>A</u> : <u>790</u> Feet From The <u>North</u> Line and <u>790</u> Feet From The <u>East</u> Line Section <u>31</u> Township <u>31N</u> Range <u>11W</u> NMPM San Juan County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ Cancel Plug Back

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This notice is to correct our Sundry dated July 1, 1994. Amoco Production Company does not intend to plug back the Dakota zone on the subject well per the approved Notice of Intent dated May 28, 1992.

We request approval to keep this well in shut-in status pending future workover and recompletion possibilities budgeted for 1995.

If there are any questions, please contact Dallas Kalahar at (303) 830-5129.

RECEIVED
JUL 8 1994
OIL CON. DIV.
DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dallas Kalahar TITLE Staff Business Analyst DATE 07-06-1994
TYPE OR PRINT NAME Dallas Kalahar TELEPHONE NO. (303) 830-5129

(This space for State Use)

APPROVED BY Charles Sholton TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JUL - 8 1994

CONDITIONS OF APPROVAL, IF ANY: