

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

AUG 7 1995

5. Lease Designation and Serial No.

14-20-604-90

6. If Indian, Allottee or Tribe Name

UTE MOUNTAIN

7. If Unit or CA, Agreement Designation

B.O.A. KASH-UTE MOUNTAIN B

8. Well Name and No.

#15

9. API Well No.

10. Field and Pool, or Exploratory Area

VERDE GALLUP

11. County or Parish, State

SAN JUAN NM

Type of Well.

☒ Oil Well ☐ Gas Well ☐ Other

Name of Operator

ACTION OIL CO. INC

Address and Telephone No.

3301 E. MAIN ST. FARMINGTON NM 87402

Bureau of Land Management
Durango, Colorado

Location of Well (Footage, Sec., T., R., M., or Survey Description)

1929. FSL & 1966 PWL
31-31N-15W

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

Notice of Intent

☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☒ Other

PLUG & ABANDON

☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
Completion or Recompletion Report and Log form.)

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

RECEIVED

AUG 18 1995

SEE ATTACHED

Bureau of Land Management
Durango, Colorado

I hereby certify that the foregoing is true and correct

Signed [Signature] Title _____Date 7-21-95

(This space for Federal or State office use)

Approved by Jim Lovain Title _____

Date _____

Conditions of approval, if any:

ACTING

18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations in any manner within its jurisdiction.

*See Instruction on Reverse Side

P&A COMPLETION & PROCEDURE

RECEIVED

AUG 7, 1995

Bureau of Land Management
Durango, Colorado

UTE MOUNTAIN "B " #15 LEASE #14-20-604-90

- 7/12/95 RAN 1940 OF 2 3/8 TUBING TAGGED BOTTOM APPROX. 58 JOINTS
- 7/13/95 PUMPED 65 BARRELS FRESH WATER, TRIED TO CIRULATE HOLE
- 7/14/95 PUMPED 195 BARRELS FRESH WATER TRIED TO CIRULATE, NO CIRULATION
MIXED UP 20 SACKS OF PORTLAND CEMENT WITH 3.5 BARRELS OF WATER
(A WEIGHT OF 13.5 LBS. PER INCH).
- 7/17/95 WENT BACK DOWN TO TAG BOTTOM PLUG CAME UP HOLE 16'9 HOOKED UP AND
TRIED TO CIRULATE WITH 35 BARRELS OF FRESH WATER, NO CIRULATION.
MIXED UP 25 SACKS OF PORTLAND CEMENT WITH 4 BARRELS OF WATER (A
TOTAL OF 6 BARRELS AND A WEIGHT OF 13.8 LBS PER INCH), PULLED OFF
BOTTOM 160 TO LET PLUG SET.
- 7/18/95 WENT BACK DOWN TO TAG BOTTOM, SECOND MIX OF 6 BARRELS CAME UP HOLE
57' (NOW HAVE 73"9 OF PLUG)
MIXED UP 3RD MIX OF PORTLAND CEMENT A TOTAL OF 4.5 BARRELS OF
FRESH WATER WITH 30 SACKS OF PORTLAND CEMENT (A TOTAL OF 7 BARRELS
AT A WEIGHT OF 13.7 LBS PER INCH. PULLED 416' OFF BOTTOM TO LET PLUG SET
UP. A SIGN OF FLUID 70' FROM SURFACE.
- 7/19/95 WENT BACK DOWN TO TAG BOTTOM 3RD MIX CAME UP HOLE ON ADDITIONAL 208'
(NOW HAVING BOTTOM PLUG A TOTAL OF 281'9"). PULLED OFF BOTTOM CIRULATED
HOLE WITH 20 BARRELS OF FRESH WATER. MIXED UP POTASSIUM CHLORIDE (26 SACKS
OF POTASSIUM CHLORIDE WITH 25 BARRELS OF FRESH WATER) MAKING A TOTAL
WEIGHT OF 9 LBS. PUMPED 23 BARRELS DOWN HOLE, PULLED ALL BUT 8 JOINTS
OF TUBING.
- 7/20/95 MIXED UP 33 SACKS OF PORTLAND CEMENT WITH 6 BARRELS OF FRESH WATER (A
WEIGHT OF 13.7 LBS PER INCH). PUMPED IN HOLE TILL GOOD CEMENT CAME TO
SURFACE, PULLED REMAINING 8 JOINTS OF 2 3/8 TUBING, THEM FILLED HOLE TO
THE TOP ESTIMATED 252' SURFACE PLUG.
PLUGGED & ABANDONED 7/20/95.

Action Oil Co., Inc.
Ute Mountain Ute Lease 14-20-604-90
Ute Mountain B No. 15
NE SW Sec. 31, T. 31 N., R. 15 W.
San Juan County, New Mexico

Conditions of Approval - Subsequent Report of Abandonment

1. Approval of this Notice is for the down-hole plugging of the well. Surface reclamation must be completed in accordance with Ute Mountain Ute Tribe/BIA requirements. Please contact Steve Graham, Ute Mtn. Agency (970-565-8471) for specific reclamation requirements and seed mixtures.
2. When the wellsite is ready for final surface inspection, please contact this office and BIA in order that an onsite inspection can be made. Final Abandonment Notice (FAN) can be submitted via Sundry Notice at that time.
3. After the FAN is approved by this office, your liability associated with the subject well will terminate.