

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

2. NAME OF OPERATOR
Tenneco Oil Company

3. ADDRESS OF OPERATOR
Box 3249, Englewood, CO 80155

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1840' FSL, 1100' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF

RECEIVED

OCT 27 1982

U. S. GEOLOGICAL SURVEY
FEDERAL BUREAU OF REVENUE

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

5. LEASE
SF-078097

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Thurston Com A

9. WELL NO.
1E

10. FIELD OR WILDCAT NAME
Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 31, T31N, R11W

12. COUNTY OR PARISH
San Juan

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
5915' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

10/20/82: Reached TD of 7069' @ 11:15 am, 10/20/82. Log 7042 to 7". Mix mud to 5% LCM, wash 120' to btm. C&C, sht trip, no fill.

10/21/82: RU & run 3 jts 4-1/2" 11.6# & 63 jts 10.5# K-55 ST&C csg (2,666'), land @ 7069', LC @ 7024' & liner hanger @ 4402'. Could not circ hole due to bridge off above liner hanger. Cmt w/175 sx (361 CF) C1-B + 2% D-79 + 1/4#/sx celloflake + 150 sx (177 CF) C1-B neat, all preceded by CW 1000. PD @ 4:00 pm, 10/21/82, LDDP & DC's, ND collar. Rig released @ 10:15 pm, 10/21/82.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Denise Wilson TITLE Production Analyst DATE October 26, 1982

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

ACCEPTED FOR RECORD

NOV 3 1982

*See Instructions on Reverse Side

FARMING

BY SM