

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other
- 
2. NAME OF OPERATOR  
Southland Royalty Company
- 
3. ADDRESS OF OPERATOR  
P.O. Drawer 570, Farmington, N.M. 87401
- 
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1665' FSL & 925' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>

ABANDON\* ☐ ☐  
(other) Perforation & Stimulation X  
Production Tubing Report X

SUBSEQUENT REPORT OF:

ation	X	<input type="checkbox"/>
report	X	<input type="checkbox"/>

5. LEASE  
NM-6890

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Reese Mesa

9. WELL NO.  
7

10. FIELD OR WILDCAT NAME  
Undesignated Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR  
AREA  
Section 11, T32N, R8W

12. COUNTY OR PARISH San Juan	13. STATE New Mexico
----------------------------------	-------------------------

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
7100' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

3/17/81 Perforated at: 3888', 3898', 3908', 3946', 3956', 3966', 3976',  
3986', 3996', 4006', 4016', 4026', 4036', 4046', 4056', 4066', 4076',  
4086', 4096' (19 holes).  
Frac'd with 203,450 gals slick water and 184,000# 20/40 sand.  
AIR 40 BPM, ATP 1700 psi, ISIP 500 psi.

3/18/81 Landed 4075' of 1-1/2", 2.90#, CSR tubing at 4086'.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

**18.** I hereby certify that the foregoing is true and correct

SIGNED Ethel Dyer TITLE Drilling Clerk DATE March 20, 1981

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

RECEIVED FOR RECORD  
MAR 24 1981  
FARMINGTON DISTRICT  
BY CEP