## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5.	LEASE
	SF-078146
5	IF INDIAN ALL OTTEF OR TRIBE NAME

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir, Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas X other	<u>Culpepper Martin</u>
well — well — other	9. WELL NO.
2. NAME OF OPERATOR	16E  10. FIELD OR WILDCAT NAME
Southland Royalty Company 3. ADDRESS OF OPERATOR	Basin Dakota
P.O. Drawer 570, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Section 4, T31N, R12W
AT SURFACE: 1020' FSL & 1610' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	60.39. GL .
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	Marie 1. Sept. 200
TEST WATER SHUT-OFF	A Line American
SHOOT OR ACIDIZE	
REPAIR WELL	GOODTE: Report results of multiple completion or zone
PULL OR ALTER CASING  MULTIPLE COMPLETE	change on Form 9-330.)
	C 50°°
CHANGE ZONES	M. M.
(other) Re-Seeding X	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent	rectionally drilled, give subsurface locations and
9-11-82	
"Re-seeding has been completed as per stipula	tion."
Subsurface Safety Valve: Manu. and Type  18. I hereby certify that the foregoing is true and correct  SIGNED   SIGNED	_
(This space for Federal or State offi	Ce use)
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE

\*See Instructions on Reverse Side

OCT 14 1982

