UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Budget Bureau No. 42-R1424
	5. LEASE SF 079353
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
nt	7. UNIT AGREEMENT NAME
	San Juan 32-8 Unit
	8. FARM OR LEASE NAME San Juan 32-8 Unit
	9. WELL NO. #49
	10. FIELD OR WILDCAT NAME Blanco MV/Undesignated PC
7	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 15, T32N, R8W
	12. COUNTY OR PARISH 13. STATE San Juan N.M.
Ε,	14. API NO. 30-045-25394
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6988' KB

SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	San Juan 32-8 Unit
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME San Juan 32-8 Unit
1. oil gas Other	9. WELL NO.
well well wother	#49
2. NAME OF OPERATOR Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME
P ADDRESS OF OPERATOR	Blanco MV/Undesignated PC
P.O. Box 90, Farmington, N.M. 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	Sec 15, T32N, R8W
below.)	12. COUNTY OR PARISH 13. STATE
AT SURFACE: 810 FNL & 810 FEL NE/NE	San Juan N.M.
AT TOP PROD. INTERVAL: 810 FNL & 810 FEL AT TOTAL DEPTH: 810 FNL & 810 FEL	14. API NO.
	30-045-25394
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REPORT, OR OTHER DATA	6988' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	The second street of the secon
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
PULL OR ALTER CASING	
MULTIPLE COMPLETE	
ARANDON*	
(other) Location Clean Up	100 100 100 100 100 100 100 100 100 100
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertined.)	ite all pertinent details, and give pertinent dates, directionally drilled, give subsurface locations and ent to this work.)*
Location clean up and reseeding completed on	8-29-83
	V ***
•	
	•
	0 1 0 E
Subsurface Safety Valve: Manu. and Type	Set @ F
18. I hereby certify that the foregoing is true and correct	0.20.93
SIGNED Nonna J Braco TITLE Production	Clerk DATE
Donna Jarace (This space for Federal or State	office use) DA ACCEPTED FOR RECORD
APPROVED BY TITLE	DAÉUVAL ・
CONDITIONS OF APPROVAL, IF ANY	- AF 1083
	OCT 05 1983

*See Instructions on Reverse Side

FARMINGTON RESOURCE AREA
BY