

F

30-045-28105

08-08-90

F. Loc. 1470/S; 1570/W Elev. 5897 GL Spd. _____ Cu. ft. _____ Comp. _____ ID _____ PB _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Per. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS	NITD	X	Well Log	TEST DATA						
Ojo Alamo	C-103		Plat X	Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland	C-104		Electric Log							
Fruitland			C-122							
Pictured Cliffs	Ditr		Dfa							
Chacra	Datr		Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										
	W/304.41 Acres									

P
o
o

Basin Fr Coal Co. SJ S 21 T 31N R 11W U K Oper. Amoco Production Co. Lse. Mudge B No. 62

Mudge B #62

K-21-31N-11W

AMOCO PRODUCTION CO.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



IN REPLY REFER TO

SF-078336-B et al. (WC)
3162.3-1 (019)

Amoco Production Company
P.O. Box 800
Denver, CO 80201

OCT. 18 1991

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

- ✓ 1. 14 Barrett A, sec. 19, T. 31 N., R. 9 W., San Juan County, NM,
lease SF-078336-B.
- ✓ 2. 64 Mudge B, sec. 20, T. 31 N., R. 11 W., San Juan County, NM,
lease SF-078096.
- ✓ 3. 62 Mudge B, sec. 21, T. 31 N., R. 11 W., San Juan County, NM,
lease SF-078096.
- ✓ 4. 1 Florance Gas Com H, sec. 30, T. 30 N., R. 9 W., San Juan County, NM,
lease SF-077833.
- ✓ 5. 11 Heaton A, sec. 28, T. 31 N., R. 11 W., San Juan County, NM,
lease SF-078097.

As discussed with Cindy Burton of your company on, October 9, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

CC:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

RECEIVED

OCT 21 1991

OIL CON. DIV.
DIST 3

ABANDONED LOCATION