## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0135

FARMINGTON DISTRICT OFFICE

BU	JREAU OF LAND	MANAGEMENT	BLM	EXPIRES: July 31, 1996
				5. Lease Serial No.
SUNDRY	NOTICES AND I	REPORTS ON WEL	<b>19</b> 20 PN 12: 26	NM83503
Do not use this form				6. If Indian, Allottee or Tribe Name
abandoned well	II. Use form 3160	-3 (APD) for such pi	oposais.	4
	IPLICATE - Other	instruction of reve	ISE SIGE	7. If Unit or CA/ Agreement, Name and/or No.
ype of Well  Oil Well  X Gas Well	1	Otiar	E Contractor	The many
Oil Well X Gas Well		لير	ICUSIE IN WE	
lame of Operator		- Mi	to the second	4. Viris Name and No.
CNG PRODUCING COMPANY		n n	OCT 2 8 1000	GRASSY CANYON #4 (CNG #3955)
Address		3b. Phone No. (include an	na code)	9. API Well No.
1450 POYDRAS ST, NEW ORLEAN	NS, LA 70112-6000	(504) 593-7080	ID /30 no	30-045-28480
ocation of Well (Footage, Sec., T., R., M.,	or Survey Description)	ישני	R GONT DU	107 Field and Pool, or Exploratory Area
Surface: 834' FNL & 2,505' FEL of	f Sec. 31-T32N-R7W		DIST, 3	L/OBASIN FRUITLAND COAL
Bottom hole location: 1,047 FNL &	& 1,605' FWL of Sec. 3'	1-T32N-R7W	டிரும் இ	11. County or Periah, State SAN JUAN, NEW MEXICO
40 OUTOK ADDI	DODDIATE BOY/S	SY TO INDICATE N	ATURE OF NOTICE RE	PORT, OR OTHER DATA
	RUPKIATE BUX	23) TO INDICATE IN	TYPE OF ACTION	. OKT, OK OTHER DIKE
TYPE OF SUBMISSION	<u> </u>		THEOFACTION	
	Acidize	Deepen	Production (Start/Resume)	Water Shul-Off
X Notice of Intent				
X Notice of Intent	Alter Casing	Frecture Treat	Reclamation	Well integrity
Subsequent Report			<u>ا</u>	<del></del>
	Casing Repair	New Construction	Recomplete	X Ohe CAVITATION WORK AND WORKOVER
Final Abandonment Notice	_ • •	لبييا		
	Change Plans	Plug and Abandonment	Temporarily Abandon	
		_	_	
	Convert to Injection	Plug Sack	VVater Disposel	
thereof. If the proposal is to deepe and zones. Attach the Bond under 30 days following completion of the once testing has been completed, has determined that the site is read	en directionally or recor ir which the work will be a involved operationa. Final Abandonment N dy for final inspection.)	mplete horizontally, give so performed or provide the If the operation results in a otices shall be filed only a	ubsurface locations and measu Bond No. on file with BLM/BIA a multiple completion or recom fter all requirements, including	of any proposed work and approximate duration ared and true vertical depths of all pertinent marker Required subsequent reports shall be filed within pletion in a new interval, a Form 3160-4 shall be fil reclamation have been completed, and the operat
thereof. If the proposal is to deepe and zones. Attach the Bond under 30 days following completion of the once testing has been completed. has determined that the site is read SUMMARY OF OPERATIO.  Cleaned up well from 3,865' to 3,97,80P. Ran cavitation cycles 8, 9, 1 lines clean. Pumped fluid to unpluy hole at 3,865'. Make very large vo Gas rate estimated an improvement 12,13. Pridned off. Driller failed to	en directionally or recorer which the work will be a involved operationa. Final Abandonment Nody for final inspection.)  ONS FOR OCTOBE  125°. Ran flow test on 3  10 & 11. Hole bridged and bridge. Trip in hole, in the properties of coal recoveries at 600 - 750 MCF/D. For close 2 7/8° pipe ram.	mpiete horizontally, give so performed or provide the performed or provide the if the operation results in a otices shall be filed only a ER 10, 1998 - OCTO  V4" positive ck - 25 PSIG. off on #10. Blind rams we hit several light bridges. Cleaned and circulate inished cleaning out hole. Blew 3 its of drill pipe out.	Bourface locations and measurements and measurements. Bond No. on file with BLM/BIA and multiple completion or recommenter all requirements, including BER 16, 1998.  Gas rate of 517 MCF/D in 1 have plugged with coal cuttings. Circulated large volumes of coad hole from 3,865' to 3,925'. Vito 3,925'. Flow tested at 890 at of hole. Secured well with bill.	red and true vertical depths of all pertinent marker Required subsequent reports shall be filed withi pletion in a new interval, a Form 3160-4 shall be fil
thereof. If the proposal is to deepe and zones. Attach the Bond under 30 days following completion of the once testing has been completed. has determined that the site is read SUMMARY OF OPERATIO  Cleaned up well from 3,865' to 3,92 BOP. Ran cavitation cycles 8, 9, 1 lines clean. Pumped fluid to unpluphole at 3,865'. Make very large vo Gas rate estimated an improvement 12-13. Bridged off. Driller failed to rig for operations. Trip in hole, cut	en directionally or recore which the work will be a involved operationa. Final Abandonment New York final Abandonment New York final inspection.)  ONS FOR OCTOBE  125'. Ran flow test on 3 10 & 11. Hole bridged ag bridge. Trip in hole, to blumes of coal recoverient 600 - 750 MCF/D. For close 2 7/8" pipe rame and slipped drilling line.	mpiete horizontally, give so performed or provide the performed or provide the if the operation results in a otices shall be filed only a ER 10, 1998 - OCTO  V4" positive ck - 25 PSIG. off on #10. Blind rams we hit several light bridges. Cleaned and circulate inished cleaning out hole. Blew 3 its of drill pipe out.	Bond No. on file with BLM/BIA a multiple completion or recom iter all requirements, including  BER 16, 1998  Gas rate of 517 MCF/D in 1 h re plugged with coal cuttings. Circulated large volumes of coal d hole from 3,965' to 3,925'. V to 3,925'. Flow tested at 890 at of hole. Secured well with bl led fill at 3,860'. Cleaned hole  Title  REGULATORY REPO	red and true vertical depths of all pertinent marker.  Required subsequent reports shall be filed withi pletion in a new interval, a Form 3160-4 shall be fil reclamation have been completed, and the operat or. Trip out of hole with single drill pipe in Pumped and flushed the rams and choke al, cleaning at 3,865°. Circulate and cleaned Vell still recovering large volume of coal.  MCF/D. Pull out of hole. Cavitated cycles lind rams. Finished repairing and preparing
thereof. If the proposal is to deepe and zones. Attach the Bond under 30 days following completion of the once testing has been completed. has determined that the site is read SUMMARY OF OPERATIO.  Cleaned up well from 3,865' to 3,92 BOP. Ran cavitation cycles 8, 9, 1 lines clean. Pumped fluid to unpluy hole at 3,865'. Make very large vo Gas rate estimated an improvement 12-13. Bridged off. Driller failed to rig for operations. Trip in hole, cut coal volume returns.  4. I hereby certify that the forgoing is Name (Printed/Typed)	en directionally or recor ir which the work will be e involved operations.  Final Abandonment Ni dy for final inspection.)  ONS FOR OCTOBE  125°. Ran flow test on 3 10 & 11. Hole bridged a ug bridge. Trip in hole, to lolumes of coal recoverie int 600 - 750 MCF/D. Fo o close 2 7/8" pipe ram at and slipped drilling line	mpiete norizontally, give so performed or provide the performed or provide the if the operation results in a otices shall be filed only a ER 10, 1998 - OCTO  Wiff positive ck - 25 PSIG. off on #10. Blind rams we hit several light bridges. (es. Cleaned and circulate finished cleaning out hole. Blew 3 its of drill pipe of e. Tripped down and tagg	a multiple completion and measurements and measurements. Including the all requirements, including the all requirements, including the all requirements, including the all requirements, including the all requirements and cuttings. Circulated large volumes of coad hole from 3,865 to 3,925'. Vito 3,925'. Flow tested at 890 at of hole. Secured well with blood fill at 3,860'. Cleaned hole this at 3,860'. Cleaned hole this at 3,860'. Cleaned hole this at 3,860'. Title REGULATORY REPORTS.	ared and true vertical depths of all pertinent marker.  Required subsequent reports shall be filled within pletion in a new interval, a Form 3160-4 shall be fill reclamation have been completed, and the operation.  Trip out of hole with single drill pipe in Pumped and flushed the rams and choke all, cleaning at 3,865°. Circulate and cleaned Vell still recovering large volume of coal.  MCF/D. Pull out of hole. Cavitated cycles lind rams. Finished repairing and preparing from 3,860° to 3,865°. Getting large
thereof. If the proposal is to deepe and zones. Attach the Bond under 30 days following completion of the once testing has been completed. has determined that the site is read SUMMARY OF OPERATIO.  Cleaned up well from 3,865' to 3,95 BOP. Ran cavitation cycles 8, 9, 1 lines clean. Pumped fluid to unpluy hole at 3,865'. Make very large vo Gas rate estimated an improvement 12-13. Bridged off. Driller failed to rig for operations. Trip in hole, cut coal volume returns.  1. I hereby certify that the forgoing is Name (Printed/Typed)  SUSAN H. SACHITANA  Signature	en directionally or recor ir which the work will be e involved operations.  Final Abandonment Ni dy for final inspection.)  ONS FOR OCTOBE  125°. Ran flow test on 3 10 & 11. Hole bridged a ug bridge. Trip in hole, to lolumes of coal recoverie int 600 - 750 MCF/D. Fo o close 2 7/8" pipe ram at and slipped drilling line	mpiete norizontally, give so performed or provide the performed or provide the if the operation results in a otices shall be filed only a ER 10, 1998 - OCTO  Wiff positive ck - 25 PSIG. off on #10. Blind rams we hit several light bridges. (es. Cleaned and circulate finished cleaning out hole. Blew 3 its of drill pipe of e. Tripped down and tagg	Bond No. on file with BLM/BIA a multiple completion or recom iter all requirements, including  BER 16, 1998  Gas rate of 517 MCF/D in 1 h re plugged with coal cuttings. Circulated large volumes of coal d hole from 3,965' to 3,925'. V to 3,925'. Flow tested at 890 at of hole. Secured well with bl led fill at 3,860'. Cleaned hole  Title  REGULATORY REPO	ared and true vertical depths of all pertinent marker.  Required subsequent reports shall be filled within pletion in a new interval, a Form 3160-4 shall be fill reclamation have been completed, and the operation. Trip out of hole with single drill pipe in Pumped and flushed the rams and choke all, cleaning at 3,865°. Circulate and cleaned Vell still recovering large volume of coal.  MCF/D. Pull out of hole. Cavitated cycles lind rams. Finished repairing and preparing from 3,860° to 3,865°. Getting large
thereof. If the proposal is to deepe and zones. Attach the Bond under 30 days following completion of the once testing has been completed. has determined that the site is read SUMMARY OF OPERATIO.  Cleaned up well from 3,865' to 3,95 BOP. Ran cavitation cycles 8, 9, 1 lines clean. Pumped fluid to unpluy hole at 3,865'. Make very large vo Gas rate estimated an improvement 12-13. Bridged off. Driller failed to rig for operations. Trip in hole, cut coal volume returns.  I. I hereby certify that the forgoing is Name (Printed/Typed).	en directionally or recor ir which the work will be e involved operations. Final Abandonment Ni ody for final inspection.)  ONS FOR OCTOBE  125°. Ran flow test on 3 10 & 11. Hole bridged ug bridge. Trip in hole, tolumes of coal recoverie ent 600 - 750 MCF/D. Fo to close 2 7/8" pipe ram at and slipped drilling line is true and correct	mpiete norizontally, give so performed or provide the performed or provide the if the operation results in a otices shall be filed only a ER 10, 1998 - OCTO  Wiff positive ck - 25 PSIG. off on #10. Blind rams we hit several light bridges. (es. Cleaned and circulate finished cleaning out hole. Blew 3 its of drill pipe of e. Tripped down and tagg	Bond No. on file with BLM/BIA a multiple completion or recom filer all requirements, including BER 16, 1998  Gas rate of 517 MCF/D in 1 h are plugged with coal cuttings. Circulated large volumes of coal d hole from 3,865' to 3,925'. V to 3,925'. Flow tested at 890 at of hole. Secured well with bi led fill at 3,860'. Cleaned hole  Title  REGULATORY REPO Date  981016  OR STATE OFFICE US	ared and true vertical depths of all pertinent marker.  Required subsequent reports shall be filled within pletion in a new interval, a Form 3160-4 shall be fill reclamation have been completed, and the operation. Trip out of hole with single drill pipe in Pumped and flushed the rams and choke all, cleaning at 3,865°. Circulate and cleaned Vell still recovering large volume of coal.  MCF/D. Pull out of hole. Cavitated cycles lind rams. Finished repairing and preparing from 3,860° to 3,865°. Getting large
thereof. If the proposal is to deepe and zones. Attach the Bond under 30 days following completion of the once testing has been completed. has determined that the site is read SUMMARY OF OPERATIO.  Cleaned up well from 3,865' to 3,95 BOP. Ran cavitation cycles 8, 9, 1 lines clean. Pumped fluid to unpluy hole at 3,865'. Make very large vo Gas rate estimated an improvement 12-13. Bridged off. Driller failed to rig for operations. Trip in hole, cut coal volume returns.  I hereby certify that the forgoing is Name (Printed/Typed)  SUSAN H. SACHITANA Signature	en directionally or recor ir which the work will be e involved operations. Final Abandonment Ni ody for final inspection.)  ONS FOR OCTOBE  125°. Ran flow test on 3 10 & 11. Hole bridged ug bridge. Trip in hole, tolumes of coal recoverie ent 600 - 750 MCF/D. Fo to close 2 7/8" pipe ram at and slipped drilling line is true and correct	priefe horizontally, give so performed or provide the performed or provide the if the operation results in a otices shall be filed only a ER 10, 1998 - OCTO  Off on #10. Blind rams we hit several light bridges. Ces. Cleaned and circulate finished cleaning out hole. Blew 3 its of drill pipe on e. Tripped down and tagg	Bond No. on file with BLM/BIA a multiple completion or recom filer all requirements, including BER 16, 1998  Gas rate of 517 MCF/D in 1 h are plugged with coal cuttings. Circulated large volumes of coal d hole from 3,865' to 3,925'. V to 3,925'. Flow tested at 890 at of hole. Secured well with bi led fill at 3,860'. Cleaned hole  Title  REGULATORY REPO Date  981016  OR STATE OFFICE US	ared and true vertical depths of all pertinent marker.  Required subsequent reports shall be filled within pletion in a new interval, a Form 3160-4 shall be fill reclamation have been completed, and the operation.  Trip out of hole with single drill pipe in Pumped and flushed the rams and choke al, cleaning at 3,865°. Circulate and cleaned Vell still recovering large volume of coal.  MCF/D. Pull out of hole. Cavitated cycles lind rams. Finished repairing and preparing from 3,860° to 3,865°. Getting large
thereof. If the proposal is to deepe and zones. Attach the Bond under 30 days following completion of the once testing has been completed. has determined that the site is read SUMMARY OF OPERATIO  Cleaned up well from 3,865' to 3,97,80P. Ran cavitation cycles 8, 9, 1 lines clean. Pumped fluid to unpluy hole at 3,865'. Make very large vo Gas rate estimated an improvemer 12-13. Bridged off. Driller failed to rig for operations. Trip in hole, cut coal volume returns.  I hereby certify that the forgoing is Name (Printed/Typed)  SUSAN H. SACHITANA  Signature  Approved by	en directionally or recor ir which the work will be e involved operations. Final Abandonment Ni ody for final inspection.)  ONS FOR OCTOBE  125°. Ran flow test on 3 10 & 11. Hole bridged ug bridge. Trip in hole, tolumes of coal recoverie ent 600 - 750 MCF/D. Fo to close 2 7/8" pipe ram at and slipped drilling line is true and correct	price horizontally, give so performed or provide the performed or provide the if the operation results in a otices shall be filed only a ER 10, 1998 - OCTO  We' positive ck - 25 PSIG. off on #10. Blind rams we hit several light bridges. (es. Cleaned and circulate finished cleaning out hole. Blew 3 its of drill pipe of e. Tripped down and tagg	Bond No. on file with BLM/BIA multiple completion or recommendate and requirements, including BER 16, 1998  Gas rate of 517 MCF/D in 1 have plugged with coal cuttings. Circulated large volumes of coad hole from 3,865' to 3,925'. Vito 3,925'. Flow tested at 890 at of hole. Secured well with bled fill at 3,860'. Cleaned hole REGULATORY REPORTS.  Title  REGULATORY REPORTS.  Title  OR STATE OFFICE US	ared and true vertical depths of all pertinent marker. Required subsequent reports shall be filled within pletion in a new interval, a Form 3160-4 shall be fill reclamation have been completed, and the operation. Trip out of hole with single drill pipe in Pumped and flushed the rams and choke all, cleaning at 3,865°. Circulate and cleaned Vell still recovering large volume of coal.  MCF/D. Pull out of hole. Cavitated cycles lind rams. Finished repairing and preparing from 3,860° to 3,865°. Getting large  RTS ADMINISTRATOR  Date  ACCEPTED FOR RECC
thereof. If the proposal is to deepe and zones. Attach the Bond under 30 days following completion of the once testing has been completed. has determined that the site is read SUMMARY OF OPERATIO.  Cleaned up well from 3,865' to 3,95 BOP. Ran cavitation cycles 8, 9, 1 lines clean. Pumped fluid to unpluy hole at 3,865'. Make very large vo Gas rate estimated an improvement 12-13. Bridged off. Driller failed to rig for operations. Trip in hole, cut coal volume returns.  Thereby certify that the forgoing is Name (Printed/Typed)  SUSAN H. SACHITANA Signature	en directionally or recor ir which the work will be e involved operations. Final Abandonment Ni ody for final inspection.)  ONS FOR OCTOBE  125°. Ran flow test on 3 10 & 11. Hole bridged ug bridge. Trip in hole, tolumes of coal recoverie ent 600 - 750 MCF/D. Fo to close 2 7/8" pipe ram at and slipped drilling line is true and correct	price horizontally, give so performed or provide the performed or provide the if the operation results in a otices shall be filed only a ER 10, 1998 - OCTO  We' positive ck - 25 PSIG. off on #10. Blind rams we hit several light bridges. (es. Cleaned and circulate finished cleaning out hole. Blew 3 its of drill pipe of e. Tripped down and tagg	Bond No. on file with BLM/BIA multiple completion or recommendate and requirements, including BER 16, 1998  Gas rate of 517 MCF/D in 1 have plugged with coal cuttings. Circulated large volumes of coad hole from 3,865' to 3,925'. Vito 3,925'. Flow tested at 890 at of hole. Secured well with bled fill at 3,860'. Cleaned hole REGULATORY REPORTS.  Title  REGULATORY REPORTS.  Title  OR STATE OFFICE US	ared and true vertical depths of all pertinent marker.  Required subsequent reports shall be filled within pletion in a new interval, a Form 3160-4 shall be fill reclamation have been completed, and the operation. Trip out of hole with single drill pipe in Pumped and flushed the rams and choke all, cleaning at 3,865°. Circulate and cleaned Vell still recovering large volume of coal.  MCF/D. Pull out of hole. Cavitated cycles lind rams. Finished repairing and preparing from 3,860° to 3,865°. Getting large

or fraudulent statements or representations as to any matter within its jurisdiction.