



Key Energy Services, Inc.

Four Corners Division
P.O. Box 900
5651 US Highway 64
Farmington, NM 87499
Phone: 505-327-4935
Fax: 505-327-4962

October 17, 2000

Koch Exploration Company
P.O. Box 489
Aztec, NM 87410



This letter is to certify that Key Energy Services did run deviation surveys at the below listed depths on your Walker #2B well, in S10-T31N-R10W in San Juan county, New Mexico.

Depth	Deviation	Depth	Deviation
120'	$\frac{1}{4}^{\circ}$	1563'	$\frac{3}{4}^{\circ}$
240'	$\frac{3}{4}^{\circ}$	2064'	1°
548'	$1\frac{1}{4}^{\circ}$	2564'	$\frac{3}{4}^{\circ}$
761'	$\frac{3}{4}^{\circ}$	3346'	$\frac{3}{4}^{\circ}$

Well drilled from 3346' to 5460' with air hammer .

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith
Drilling contract manager

Notary Public

My commission expires:

10/26/02