

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well Other	5. Lease Serial No. 142060478 ✓
2. Name of Operator CROSS TIMBERS OPERATING CO.	6. If Indian, Allottee or Tribe Name
3a. Address 2700 FARMINGTON AVE., BLDG K, SUITE 1 FARMINGTON, NM 87401	7. If Unit or CA/Agreement Name and/or No.
3b. Phone No. (Area code) 505.324.1090 Ext 4007	8. Well Name and No. UTE MTN GAS COM M 2 ✓
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2030FWL 525FNL <i>Sec 11 T31N R14W</i>	9. API Well No. 3004530488 ✓
	10. Field and Pool, or Exploratory Area UTE DOME DAKOTA
	11. County or Parish, and State SAN JUAN NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input checked="" type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Cross Timbers Operating Company reached drillers total depth of 3,146' on 3/24/01. Schlumberger ran AIL/MSFL/SP/GR/cal & TLD/CNL/GR fr/3,127' (WLTD) - 1,450'. Ran 72 joints new 4 1/2", 10.5#, J-55 ST&C casing. Landed casing @ 3,149'.72'. Cemented casing w/625 sx 50/50 Type III/poz w/2% gel, 2% CaCl2 & 1/4#/sx CF (14.8 ppg, 1.54 cuft/sx). Circulated 10 barrels cement to surface. Released rig @ 12:00 a.m. (MST), 3/26/01. DID NOT PRESSURE TEST PRODUCTION CASING. WILL TEST AT COMPLETION. SUBMITTING ENGINEER: JEFFREY W. PATTONSUBMITTAL DATE: 4/2/01

Electronic Submission #3355 verified by the BLM Well Information System for CROSS TIMBERS OPERATING CO. Sent to the Durango Field Office

Name (Printed/Typed) JEFFREY W. PATTON	Title ENGINEER
Signature	Date 04/02/01

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By	Title TG 4/12/01	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	