

7/6 - 7/12

WELL NAME AND NUMBER

SUTER # 4B

30-045-30638

LOCATION C SEC 12, T32N, R11W; SAN JUAN COUNTY, NEW MEXICO

(New Mexico give U, S, T, & R; Texas give S, Blk., Sur. & Twp. when required.)

OPERATOR CONOCO, INC.

DRILLING CONTRACTOR AZTEC WELL SERVICING CO., INC.

The undersigned hereby certifies that he is an authorized representative of the drilling contractor who drilled the above-described well and that he has conducted deviation tests and obtained the following results:

Degrees @ Depth

Degrees @ Depth

Degrees @ Depth

Degrees @ Depth

3/4° @ 298'

1/2° @ 750'

1° @ 1241'

1/2° @ 1735'


3/4° @ 2234'

1/2° @ 2593'

Drilling Contractor AZTEC WELL SERVICING CO.,
INC.

By

Subscribed and sworn to before me this 11TH day of SEPTEMBER, 10 2001



Notary Public

My Commission Expires

6/30/02

SAN JUAN County, NEW MEXICO

OIL CONSERVATION DIVISION

1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 09/02/2001 Operator Burlington Resources Oil & Gas

Lease Name SAN JUAN 27-5 UNIT Well No 110 Location: U B Sec. 02 Twp. 027N Rge. 005W

Pressure () Flowing () Dwt Tubing 140 Intermediate Casing 278 Bradenhead 392

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME: PRESSURES: INTERMEDIATE CASING
5 Min. 276 Steady Flow X
10 Min. 270 Surges
15 Min. 263 Down to Nothing
20 Min. 260 Nothing
25 Min. 260 Gas X
30 Min. 260 Gas & Water
Water

BRADENHEAD FLOWED:
INTERMEDIATE FLOWED:

If Bradenhead flowed water, check description below:

Clear
Fresh
Salty
Sulfur
Black
Remarks: Whisper Vapor Too Small To Measure At the end of the Bradenhead 5 min. shut in the press. was 2

By GERALD REEVES
Lease Operator
Witness
Position

306

