



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. **MS-021125**

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ohio Gov't. Sec. 18
Well No. **1** is located **910** ft. from **N** line and **930** ft. from **E** line of sec. **18**
NE (1/4 Sec. and Sec. No.) **215** (Twp.) **12W** (Range) (Meridian)
La Plata (Field) **San Juan** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

235' TD. W. O. C. 3/4 Sug. at 200'. Run 7 joints 10-1/4", 32.75# casing. Set 215'. Set at 220' ES. Cemented with 100 sacks. Plugged down at 3:30 a.m.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **The Ohio Oil Company**

Address **P. O. Box 100**

Casper, Wyoming

By _____

Title **Division Superintendent of Production**

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000



100-100000