(April 1952)			
		×	

(SUBMIT IN TRIPLICATE)

UNITED STATES

0.11.1.20				
DEPARTMENT	OF	THE	INTE	RIOR
CEO! OC				n n

Indian Agency	avajo
14-20-603-5	92
Allottee	

GEOLOGICAL SURVEY

Co. Losse No. 221461

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL.	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	
NOTICE OF INTENTION TO ABANDON WELL.	Subsequent report of DST

(INDICATE AI	BOVE BY CHECK MAR	K NATURE OF REPORT	, NOTICE, OR OTHER I	DATA	
UMBLE & CONTINENTAL BAVAJO TRIBE OF INDIANS *B*		Fermington,	New Mexico	November 14,	, 19 <u> </u>
Well Nois locate	ed 1650 ft. f	$\operatorname{rom} \left\{ \begin{array}{c} \mathbf{S} \\ \mathbf{S} \end{array} \right\}$ line and	d 1650 ft. fro	om E line of sec.	30
MM/4 3E/4 Section 30	T-32-N	n-20-₩			
(14 Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)		
Four Corners Paradog	3	en Juen	H	ev Mexico	
(Field)	(Count	y or Subdivision)		(State or Territory)	
	_	4713	_		

The elevation of the derrick floor above sea level is _____ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

11/8/56: DST #1 from 5385 to 5445 w/1" TC # 3/4" BC. TO 1 hr. deak blew throughout test. Recovered 5' alightly gas out drig, and. Both recorders failed to make pressure chart. Bottom hole temp. 133".

11/11/56: DS #2 from 5437 to 5501 w/1" TC & 3/4" BC. TO 3 hrs. Good blow throughout test. Recovered 40' slightly oil & gas cut mad, 253' heavy oil & gas out mud, 1307' ealt water. In 2940%. FM 2805%. Min. FF 100%, max PP 665%. Build up 2500% after 30 min. Salt content 37,000 PPM. Test satisfactory.

		A STEEL STD /
		200 V 1.5 35
I understand	that this plan of work must receive approval in writing by t	Geological Survey before operations may be commenced.
Company	Hamble Call & Wefining Company	DIST 2
Address	Box 1268	
Addicss	Farmington, New Hunice	By Russell M. LILLY
<u> </u>		Title
	THE CONTRACT PRINTING ASSESSMENT BUILDING ASSES	- 1 <u>e 0427h-7</u>

MA (