

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAY 10 1993

WELL API NO.

30-045-28873

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Hallwood Petroleum, Inc.

3. Address of Operator

P.O. Box 378111 Denver, CO 80237

7. Lease Name or Unit Agreement Name

Ripley 26

8. Well No.

3

9. Pool name or Wildcat

Basin Fruitland Coal

4. Well Location

Unit Letter H : 2195 Feet From The North Line and 805 Feet From The East Line

Section 26 Township 32N Range 13W NMPM San Juan County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

5909 KB

5897 GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☒

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-16-92 1. Spud 12-1/4" surface hole at 5:30 p.m.
12-17-92 1. Ran 8 Jts 8-5/8" 24# J-55 csg. Set at 377'.
2. Cement with 265 sxs Class "B". Pressure test csg to 800 psi for 15 min.
3. Circ 22 bbls cmt to pit.

12-19-92 1. Ran 50 Jts 5-1/2" 17# LTC J-55 csg. Guide shoe at 2133'. Ext Csg Packer
2. Cmt with 150 sxs Howco Lite & 135 sxs neat "B". at 1995'.
3. Pressure test csg to 2500 psi for 15 min.
4. 11 bbls cmt returns to pit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Lois M. Benda

TITLE Sr. Engr. Tech

DATE 5/7/93

TYPE OR PRINT NAME Lois M. Benda

TELEPHONE NO. 303-850-6285

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ

TITLE SUPERVISOR DISTRICT # 3

DATE MAY 10 1993

CONDITIONS OF APPROVAL, IF ANY: