

(SUBMIT IN TRIPPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-1334.1
Approval expires 12-31-60

Land Office **NEW MEXICO**
Lease No. **NM-020406 A**
Unit **1**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	X	SUBSEQUENT REPORT OF STOPPING OR RESUMING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CANNIS	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CANNIS		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

RECEIVED

JAN 16 1961

January 12, 1961

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO


Well No. 1 is located 660 ft. from SH line and 1980 ft. from SW line of sec. 24
(Of sec. and sec. No.) (Twp.) (Range) (Meridian)
SW/4 Sec. 24 20 N 13 W NMPH
(Field) (County or Parish) (State or Territory)

The elevation of the derrick floor above sea level is 6271 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Well to be filled with mud, 10 sacks cement spotted on bottom, 20 sacks spotted in section from 2170 to 2240 and 5 sacks in top of hole.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company United Western Minerals Company

Address 302 E. Palace Ave.

Santa Fe, New Mexico

By _____

Title _____