



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 072 24-A  
Unit 32-5 Area

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS 1959

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Report made on 6, 1958

Well No. 1-10 is located 1850 ft. from N line and 1150 ft. from E line of sec. 10  
1/4 sec. 10 32-5 10  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
10 San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7563 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cleaned out well to 4133'. Well made small quantity of gas with excessive quantity of water - hence would not flow.

Propose to plug and abandon, plugging the pictured 11' perforations (top of Pictured Cliffs at 4070') with 100 sacks of cement, leave 5-1/2" casing in the hole, and weld permanent cap on top of hole, attaching dry hole marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Santa Fe Gathering System, Inc.

Address Box 728

Farmington, New Mexico.

By [Signature]

Title Personnel, Agent in Farmington