

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 078301
Unit SE 1/4 Sec. 12
T-24N, R-10W

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

Yamb. Aband. Well ☒

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 21, 1952

Well No. 1 Duff, A. L. is located 1980 ft. from N line and 1980 ft. from E line of sec. 12
NE/4 Sec. 12 24N 10W 100W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6054 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Permission is requested to temporarily abandon the test, since the Pictured Cliffs sandstone showed water upon drill stem testing from 1818 to the total depth of 1920. The tool was open one hour and a good blow of air was had throughout. Recovered 270' of water cut drilling mud with no showings of gas. FF 70%, 15 minutes S.I.P. 380, Hydrostatic pressure 940%.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lucerne Corporation - Niles Company

Address Marquette Securities Building

Dallas 1

Texas

By [Signature]
Agent

Title _____