


(SUBMIT IN TRIPLICATE)

Indian Agency Window Rock
Arizona

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 1-140-Sub.-0100-4



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 4, 1958

Well No. 1 ~~McDonnell~~ 720 ft. from [S] line and 620 ft. from [W] line of sec. 12
SW/4 SW/4 Sec. 12 T 27 N - R 13 W MPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Window San Juan County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5045 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well plugged as follows:

From	To	Length
1175	1200	25
1000	1050	50
1150	1200	50
1300	1350	50
195	120	75
12	0	12



Pits filled, location cleaned and graded, and marker erected, and is now ready for your inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DAVIS OIL COMPANY

Address 1000 Midland Savings Bldg.

Denver 2, Colorado

By Paul Messinger

Paul Messinger

Title Engl. Mgr., Southern Div.

ILLEGIBLE