UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry	Notices and Reports on Well	ls
1. Type of Well GAS	DEGEIVED APR 1 8 1994	 5. Lease Number SF-077056 6. If Indian, All. or Tribe Name 7. Unit Agreement Name
2. Name of Operator MERIDIAN OIL 3. Address & Phone No. of O PO Box 4289, Farmington 4. Location of Well, Footag 2310'FNL, 990'FWL Sec.20	, NM 87499 (505) 326-9700 e, Sec., T, R, M	8. Well Name & Number Cozzens #4 9. API Well No. 10. Field and Pool Fulcher Kutz PC 11. County and State
12. CHECK APPROPRIATE BOX Type of Submission _x_ Notice of Intent Subsequent Report Final Abandonment	Casing Repair	
indicating integrity for well is currently non- sufficiently, this well	casing integrity; current tubing/casing pressure the wellbore is sound and no remedial action-productive due to excessively high line pressure will produce in economic quantities. We are eral, and allow the subject well to once again	on is currently required. The subject sure. Should line pressure drop e currently evaluating options to reduce
		SECEIVED SECONDS: 0
	MAY 01 1995	<u>~</u> ~ ~
	the foregoing is true and confidence (SBD) Title Regulatory Af	
(This space for Federal or APPROVED BY CONDITION OF APPROVAL, if	Title	Date Trn U V E D
CONDITION OF APPROVAL, II	MMOCD	APR 1 0 7094 ~