

APPROVED *[Signature]*
DEC 7 1953
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 065557
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	☒
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 2 is located 660 ft. from N line and 660 ft. from W line of sec. 12, 1953
27 (wp.) 200 (e) (M.L.P.A.)
San Juan (C. Jones Subdivision) New Mexico

The elevation of the derrick floor above sea level is 5725 ft. Approx.
DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Moved on cable tools on November 14, 1953 for purpose of cleaning out and shooting. Cleaned out to 2,023', Pan Schlumberger Electric Log, found bottom of pipe to be 1,899'. Shot with 220 qts. SMC on November 16th. Drilled calseal and gravel plug, unloaded hole and cleaned out to bottom. Ran 1" tubing. Well made too much water for pitot tube test, but operating on line delivers approx. the same amount as well #6 which tested 1,950 mcf per day.

Shot Record: T.D. 2,021'
T.S. 1,922'
T.O. 1,910'
T. Calseal plug 1,860'

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Carroll & Cornell
Address Box 337
Farmington, New Mexico

By *[Signature]*
Title Lease Foreman

