## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

X	Budget Bureau 42-R358.2. Approval expires 12-31-52.				
Land Offic		Tribal ND-7653			
Unit					

SUNDRY NOTICES AND REPORTS ON WELL SIL GON COM.

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	-	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	-
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING.	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	-
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	-
NOTICE OF INTENTION TO PULL OR ALTER CASING	į.	Subsequent Report of DST	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

							.≅a y	27	. 19.52
Well N	Ne Io	vaj 1	о <sup>п</sup> А <sup>н</sup> is	locate	d 1980 ft.	from ${S \atop S}$ line and	d 660 ft. from	E line of sec	34
NE	of	SRi	Sec.	34	31-N	17-K	N.M.F.	М.	
		and Sec.			(Twp.)	(Range)	(Meridian)		
	Wil	Ldon	t		San	Juan	New	Mexico	
	(	(Field)			(Cou	nty or Subdivision)	(S	state or Territory)	
			-			5006			

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## **DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, comenting points, and all other important proposed work)

DST #11 on 5-23-52 from 7792' to 7838'. Too. opened 3/4 hr. Very slight blow of air first 35 min. Recovered 15' Brlg. mud. Flowing pressure 30#. 15 minute shut in B.H.P. - 30#. Hydrostatic pressure 4340#.

1 understand	that this plan of work must receive approval in writing	by the Geological Survey before operations may be commenced.
Company	The Texas Company	
Address	P.O. Box 1221	
	Pampa, Texas	By Brownon &
		Title Asst. Dist. Supt.