

(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. _____
Form Approved _____
Land Office San Juan
Lease No. 6724
Unit Reynolds

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	XX	SUBSEQUENT REPORT OF SHOOTING OR ACIDING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIFY		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 20

Well No. Reynolds is located 854 ft. from N line and 897 ft. from E line of sec. 36

NE 1/4 Sec. 19 20N 9W N.M.P.M.
(of Sec. and Twp. No.) (Twp.) (Range) (Meridian)

San Juan San Juan New Mexico
(Town) (County or subdivision) (State & Territory)

The elevation of the derrick floor above sea level is 6522 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show plans, weights, and lengths of proposed casings; indicate casing joints, casing pipe joints, and all other important proposed work)

Please be advised that we desire to cancel the intention to drill this well. In the event we plan to drill at some future date a new intention to drill will be filed.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Reynolds Taylor Oil Corporation

Address P.O. Box 1100
Farmington, New Mexico

Original signed by
By A. R. Gibson
Title State Geologist