

PS
5-1-06 incident

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

DENIED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Chevron USA	Contact	Larry Ridenour
Address	HCR60 Box 423 Lovington, NM 88260	Telephone No.	505 396 4414
Facility Name	Vacuum Glorietta West Unit #77	Facility Type	injection well

Surface Owner	State	Mineral Owner	State	Lease No.	B-2317
---------------	-------	---------------	-------	-----------	--------

LOCATION OF RELEASE

API # 30025318720000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	35	17S	34E	2569	South	1226	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	40 water 0 oil	Volume Recovered	35 water 0 oil
Source of Release	tubing	Date and Hour of Occurrence	4-21-06 early AM	Date and Hour of Discovery	4-21-06 8:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Pat Caperton		
By Whom?	Larry Williams	Date and Hour	4-21-06 12:45 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Pinhole leak in top joint of tubing between slips and tubing valve.
Leak caused from internal corrosion.
Shut well in. Well went on vacuum approximately 4 hours later. Placed clamp over pinhole.

Describe Area Affected and Cleanup Action Taken.*
Vacuum truck was called in to pick up fluid.
Major part of the spill was contained on the location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Williams</i>	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	Approved by District Supervisor:	
Title: HES Representative	Approval Date:	Expiration Date:
E-mail Address: LCWL@chevrontexaco.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4-21-06	Phone: 505 394 1237	

* Attach Additional Sheets If Necessary

Chevron USA must replace line, by 7-21-06
incident NPRS0612141278
application pPAC

Cluck 5-1-06 returned U SPS

Sheeley, Paul, EMNRD

From: Sheeley, Paul, EMNRD **Sent:** Tue 5/2/2006 10:38 AM
To: lcwl@chevron.com
Cc: Caperton, Patricia, EMNRD; Johnson, Larry, EMNRD; Price, Wayne, EMNRD
Subject: Central Vac. Unit-Sat. 3 Injection truck line...C-141 DENIAL
Attachments:

Please submit a C-141 revision including the GPS.