


RP
1193

**XTO ENERGY
STATE N
TANK BATTERY**
Unit F, Section 10, Tws, 17 S., Rng. 34 E.
GPS: 32 51' 28" N & 103 33' 02" W

*OK to start
2/12/07
CW*

WORKPLAN



**Prepared By
Eddie Seay Consulting
February 2007**

February 8, 2007

NMOCD
ATTN: Larry Johnson
1625 French Drive
Hobbs, NM 88240


RE: XTO Energy
State N Tank Battery
Unit F, Sect. 10, Tws. 17 S., Rng. 34 E.

Mr. Johnson:

XTO just recently had an oil tank leak. Oil was picked up and area stabilized. We would like approval to begin cleanup as soon as possible. Attached is a copy of the workplan and C-141.

Looking forward to hearing from you.

Sincerely,

A handwritten signature in black ink, appearing to read "Eddie W. Seay". The signature is fluid and cursive, with a long, sweeping underline that extends to the right.

Eddie W. Seay, Agent
Eddie Seay Consulting
601 W. Illinois
Hobbs, NM 88242
(505)392-2236
seay04@leaco.net

cc: XTO Energy
Gene Hudson

WORKPLAN

General:

Leak occurred 2/2/07 losing approximately 6 bls. of oil. The fluid was picked up and work began to stabilize area. Approximately 250 sq. ft. of ground was affected.

The OCD was notified.

Groundwater:

According to State Engineer and Groundwater information, the depth of water occurs at approximately 105 feet below the surface.

Remediation Proposal:

Area was stabilized by mixing soil with fluids. Our cleanup will be to excavate contaminated soil, haul to an OCD approved facility and replace with clean soil and seed. Before backfilling, the area will be tested for TPH and Chloride to assure we meet OCD guidelines, and only after OCD approves, we will backfill and level.

The OCD will be notified of all activities and a report will be filed upon completion.

Ranking Criteria Score: 10

The site has a 1000 ppm TPH cleanup and will cleanup BTEX and Chloride per OCD.

RP

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	XTO Energy	Contact	JERRY PARKER
Address	P.O. Box 200 Edwige, NM	Telephone No.	505-441-1628
Facility Name	STATE N TANK BATTERY	Facility Type	TANK BATTERY
Surface Owner	Edson Ranches	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	10	17S	34E					

NATURE OF RELEASE

Type of Release	PROD. OIL	Volume of Release	5.5 6/5	Volume Recovered	5 6/5
Source of Release	STATE TANK	Date and Hour of Occurrence		Date and Hour of Discovery	2/2/07
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Pat Cooper		
By Whom?	<input type="checkbox"/>	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

File Work Plan 2/4/07

OIL TANK STARTED LEAKING FROM GASKET BETWEEN BOLTED SECTIONS.

Describe Area Affected and Cleanup Action Taken.*

Grassland PASTURE on west side of BATTERY.

Oil collected on area of 40' x 6' behind BATTERY location.

GARDY VARTAK picked up 5 6/5. Oil & Soil will be put on PLASTIC.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jerry Parker</i>		OIL CONSERVATION DIVISION	
Printed Name: JERRY PARKER		Approved by/District Supervisor: <i>Chris Williams</i>	
Title: PROD. FOREMAN	Approval Date:	Expiration Date:	
Date: 2/2/2007	Phone: 505-441-1628	Conditions of Approval:	Attached <input type="checkbox"/>

Attach Additional Sheets If Necessary

facility - APAC 0704334657
incident - NPAC 0704334731
application - PPAC 0704334804

RP#1193



