

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

David R. Catanach
Director, Oil Conservation Division



June 23, 2015

James A. Trujillo
Chevron USA, Inc.
JTRUJILLO@chevron.com
575-650-3602

RE: Central Vacuum Unit Battery (1RP-3687) in Unit Letter E of Section 31, Township 17 South, Range 35 East, New Mexico

Dear Mr. Trujillo,

In review of the *Closure Request RP-3687 dated June 23, 2015* submitted on the above-referenced site. The available information indicates Chevron USA, Inc. has met the requirements of 19.15.29 NMAC and no further corrective action is required.

This determination by the Oil Conservation Division does not relieve Chevron USA, Inc. of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Chevron USA, Inc. of responsibility for compliance with any federal, state, or local laws and/or regulations.

Respectfully,

Kellie Jones
Environmental Specialist