

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company	Chevron USA Inc.	Contact	Josepha DeLeon
Address	15 Smith Rd, Midland, TX.	Telephone No.	575-263-0424 Cell - 432-425-1528
Facility Name	Salado Draw Compressor Site	Facility Type	Battery

Surface Owner	Mineral Owner	API No's.
Bureau of Land Management		(see attached)

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	18&19	26S	33E					Lea

Latitude 32.020661 N Longitude -103.3700.44 W

**NATURE OF RELEASE**

Type of Release	Spill	Volume of Release	2.61 BO, 4.05 BW	Volume Recovered	6.6
Source of Release	300 bbl slop tank overflow	Date and Hour of Occurrence	05/06/2016; 1:00 AM	Date and Hour of Discovery	05/06/2016; 1:00 AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Josepha DeLeon	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

300 bbl slop tank from scrubber overflowed into lined secondary containment. Shut in compressors and called vacuum truck to remove liquids.

Describe Area Affected and Cleanup Action Taken.\*

N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Josepha DeLeon	Approved by Environmental Specialist:		
Title: HES Compliance Support - Environmental	Approval Date:	Expiration Date:	
E-mail Address: jdx@chevron.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 05/06/2016 Phone: 575-263-0424			

\* Attach Additional Sheets If Necessary

## Salado Draw Wells

<i>Name</i>	<i>API#</i>
<i>Salado Draw 18 26 33 Fed # 3H</i>	<i>30-025-42278</i>
<i>Salado Draw 18 26 33 Fed # 4H</i>	<i>30-025-42279</i>
<i>Salado Draw 19 26 33 Fed # 3H</i>	<i>30-025-42280</i>
<i>Salado Draw 19 26 33 Fed # 4H</i>	<i>30-025-42281</i>
<i>Salado Draw 29 26 33 Fed # 5H</i>	<i>30-025-42440</i>
<i>Salado Draw 29 26 33 Fed # 6H</i>	<i>30-025-42441</i>
<i>Salado Draw 29 26 33 Fed # 7 H</i>	<i>30-025-42442</i>
<i>Salado Draw 29 26 33 Fed # 8H</i>	<i>30-025-42443</i>
<i>Moose's Tooth 29 26 33 Fed Com #1H</i>	<i>30-025-42168</i>
<i>Porter Brown #1H</i>	<i>30-025-40802</i>