From: Yu, Olivia, EMNRD

To: "Lowry, Joel"; Billings, Bradford, EMNRD

Cc: Slade, Rose; Amber Groves (agroves@SLO.state.nm.us)

Subject: RE: ETC"s Jal #3 Gas Plant - Field Scrubber Dump Tanks (BGTs) & 1RP-4408 - Remediation Summary and

Closure Request

Date:Friday, December 29, 2017 8:28:00 AMAttachments:approved_1RP-4408 - Final C-141 .pdf

approved_Jal #3 - Remediation Summary and Closure Request - BGTs and 1RP-4408_Consolidated.pdf

Mr. Lowry:

The available information indicates **OPERATOR** has met the requirements of 19.15.17 NMAC and no further corrective action is required. NMOCD considers Jal #3 - Field Scrubber Dump Tanks closed.

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **1RP-4408** closed.

This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Like approval from NMSLO required for 1RP-4408.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Lowry, Joel [mailto:JLowry@trcsolutions.com]

Sent: Tuesday, December 12, 2017 10:04 AM

To: Yu, Olivia, EMNRD < Olivia. Yu@state.nm.us>; Billings, Bradford, EMNRD

<Bradford.Billings@state.nm.us>

Cc: Slade, Rose <Rose.Slade@energytransfer.com>

Subject: ETC's Jal #3 Gas Plant - Field Scrubber Dump Tanks (BGTs) & 1RP-4408 - Remediation

Summary and Closure Request

Please find attached the *Remediation Summary and Closure Request* and Final C-141 that has been prepared for the Jal #3 - Field Scrubber Dump Tanks and an associate release (1RP-4408). The site is located in Unit Letter "I", Section 32, Township 24 South, Range 37 East in Lea County, NM. If you have any questions or need any additional information, please feel free to contact Rose Slade or myself by phone or email. Thanks.

Respectfully,

Joel Lowry

Senior Project Manager



2057 Commerce Drive, Midland, TX 79703 T: 432-520-7720 | F: 432-520-7701 | C: 432-466-4450

<u>LinkedIn</u> | <u>Twitter</u> | <u>Blog</u> | <u>www.trcsolutions.com</u>