

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Blue Jay Federal #001H (1RP-4610)	Facility Type: Tank Battery
Surface Owner: Federal	Mineral Owner:
API No. 30-025-42338	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	18	20S	35E	190	South	2310	East	Lea

Latitude 32.5664367366954 Longitude -103.495571226436

NATURE OF RELEASE

Type of Release: Oil (Fire)	Volume of Release: 10 bbls	Volume Recovered: 9 bbls
Source of Release: Flare	Date and Hour of Occurrence: January 25, 2017 7:00 am	Date and Hour of Discovery: January 25, 2017 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Yu - NMOCD / Shelly Tucker BLM	
By Whom? Rebecca Haskell	Date and Hour: January 25, 2017 Time per this email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

APPROVED

By Olivia Yu at 10:15 am, Jun 15, 2018

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by fluid going through the flare causing a fire. The fire quickly extinguished itself due to the limited amount of fluid that escaped the flare.

Describe Area Affected and Cleanup Action Taken.*

The release was on location and adjacent pasture area. During initial response activities, a vacuum truck was dispatched to remove all freestanding fluids.

Remediation activities were conducted in accordance with an NMOCD-approved workplan and/or associated correspondence. Please reference the Remediation Summary and Soil Closure Request, dated June 2018, for additional details regarding remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>oy</i>	
Title: Senior HSE Coordinator	Approval Date: 6/15/2018	Expiration Date: xx/xx/xxxx
E-mail Address: rhaskell@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 6, 2018 Phone: 432-683-7443		

* Attach Additional Sheets If Necessary

1RP-4610