Good morning Mr. Adkins:

Thank you for the video. No issue with access.

In review of the bottom confirmation samples submitted February 8, 2018, NMOCD will not issue a full closure due to the chlorides remaining in place at less than 4 ft. bgs. Please be advised that 1RP-4880 will be granted a deferral for further remediation at time of abandonment.

NMSLO may have additional concerns or stipulations.

Thanks, Olivia

From: David J. Adkins <dadkins@talonlpe.com>
Sent: Tuesday, July 31, 2018 7:30 AM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Michael Barrett <mbarrett@limerockresources.com>
Subject: FW: NVANU 73

Hi Olivia,

I wanted to share this with drone video with you of the liner location stakes for the NVANU 73. Kim had the closure report completed before she left and we've just been waiting for the markers install to close this project out.

Try the link below, let me know if it doesn't work for you. The file itself is too big to directly email unfortunately.

We have the GPS for all of these Lime Rock stakes as well. I'll get a data table together so we can update the closure report.

Thank you.

David J. Adkins District Manager Artesia Office: 575.746.8768 Direct: 575.616.4022 Cell: 575.441.4835 Fax: 575.746.8905 Emergency: 866.742.0742 Web: www.talonlpe.com



From: Chris Jones
Sent: Monday, July 30, 2018 6:40 PM
To: Jacob Laird <<u>jlaird@talonlpe.com</u>>; David J. Adkins <<u>dadkins@talonlpe.com</u>>;
mbarrett@limerockresources.com
Subject: NVANU 73

Download Attachment Available until Aug 29, 2018